

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2016

Document Number:

684901162

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 331508 | 331508 | Pesicka, Conor | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|-----------------|
| | | NBL_DJBU_Inspections@NB LENERGY.COM | All Inspections |

Compliance Summary:QtrQtr: NESW Sec: 21 Twp: 5N Range: 63W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 02/26/2016 | 684900710 | | | AR | | | No |
| 01/27/2016 | 684900472 | | | AR | | | No |

Inspector Comment:

Followup inspection to inspection doc#684900710

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|-------------------------------------|
| 262917 | WELL | PR | 12/30/2010 | GW | 123-20808 | NAT'L HOG FARMS 23-21 | PR | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location**Lease Road:**

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
| | | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|----------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| BATTERY | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| CONTAINERS | SATISFACTORY | methanol | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| Spills: | | | | |
|----------------|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |

☐ Multiple Spills and Releases?

| Fencing: | | | | |
|-----------------|------------------------------|-----------------------------------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | agricultural | | |
| SEPARATOR | SATISFACTORY | barbed wire; contains ECDs, pumps | | |
| TANK BATTERY | SATISFACTORY | barbed wire | | |

| | | | | | |
|-----------------------------------|-------------------|--|-------------------------------|--------------|-------|
| Equipment: | | | | | |
| Type: Bird Protectors | # 4 | | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | | | | | |
| Corrective Action | | | | | Date: |
| Type: Emission Control Device | # 2 | | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | | | | | |
| Corrective Action | | | | | Date: |
| Type: Horizontal Heated Separator | # 2 | | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | | | | | |
| Corrective Action | | | | | Date: |
| Type: Plunger Lift | # 1 | | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | | | | | |
| Corrective Action | | | | | Date: |
| Type: Ancillary equipment | # 1 | | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | pumps- 1 methanol | | | | |
| Corrective Action | | | | | Date: |

| | | | | |
|--------------------|--------------|-----------------------------------|----------------|-----------------------|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS |
| PRODUCED WATER | 1 | 100 BBLS | PBV FIBERGLASS | 40.383260,-104.443630 |
| S/AR | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
|-------------------|--|-----------------|--|

| | |
|---------|-----------------------|
| Comment | Shared with crude oil |
|---------|-----------------------|

| | | |
|--------------------|-----------------------------------|----------------|
| Facilities: | <input type="checkbox"/> New Tank | Tank ID: _____ |
|--------------------|-----------------------------------|----------------|

| | | | | |
|-----------|---|----------|-----------|-----------------------|
| Contents | # | Capacity | Type | SE GPS |
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.383260,-104.443630 |

| | | | | |
|------|--------------|--|----------|--|
| S/AR | SATISFACTORY | | Comment: | |
|------|--------------|--|----------|--|

| | | | |
|--------------------|--|------------------|--|
| Corrective Action: | | Corrective Date: | |
|--------------------|--|------------------|--|

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|-------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
|-------------------|--|-----------------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 331508

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 262917 Type: WELL API Number: 123-20808 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead plumbed to surface

CA: _____

CA Date: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Inspector Name: Pesicka, Conor

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y _____

Comment: _____

Pilot: ON _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? In _____ Production areas stabilized ? Pass _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass _____ Subsidence over on drill pit? Pass _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Inspector Name: Pesicka, Conor

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR Y Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT