

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/11/2016  
Document Number:  
666802134  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>298068</u>	<u>335488</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

**Operator Information:**

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>PO BOX 370</u>
City:	<u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

**Compliance Summary:**

QtrQtr:	<u>SWSE</u>	Sec:	<u>26</u>	Twp:	<u>6S</u>	Range:	<u>94W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/23/2010	200240149	PR	PR	SATISFACTORY			No

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
298067	WELL	PR	01/31/2010	GW	045-17050	SAVAGE RWF 544-26	PR	<input checked="" type="checkbox"/>
298068	WELL	PR	02/26/2009	GW	045-17052	SAVAGE RWF 543-26	PR	<input checked="" type="checkbox"/>
298069	WELL	PR	12/31/2009	GW	045-17053	SAVAGE RWF 343-26	PR	<input checked="" type="checkbox"/>
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	PR	<input checked="" type="checkbox"/>
298071	WELL	PR	01/31/2010	GW	045-17055	SAVAGE RWF 434-26	PR	<input checked="" type="checkbox"/>
298072	WELL	PR	01/31/2010	GW	045-17056	SAVAGE RWF 34-26	PR	<input checked="" type="checkbox"/>
298073	WELL	PR	01/31/2010	GW	045-17057	SAVAGE RWF 533-26	PR	<input checked="" type="checkbox"/>
298074	WELL	PR	12/31/2009	GW	045-17058	SAVAGE RMV 47-26	PR	<input checked="" type="checkbox"/>
298075	WELL	PR	01/11/2010	GW	045-17059	SAVAGE RWF 433-26	PR	<input checked="" type="checkbox"/>
298076	WELL	PR	01/31/2010	GW	045-17060	SAVAGE RWF 344-26	PR	<input checked="" type="checkbox"/>

298077	WELL	PR	04/16/2011	GW	045-17061	SAVAGE RWF 44-26	PR	<input checked="" type="checkbox"/>
--------	------	----	------------	----	-----------	------------------	----	-------------------------------------

**Equipment:** Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY			
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Ancillary equipment	# 3	Satisfactory/Action Required: SATISFACTORY
Comment	2 Chemical units at wellhead, 1 chemical unit at separators	
Corrective Action	Date: _____	
Type: Horizontal Heated Separator	# 11	Satisfactory/Action Required: SATISFACTORY

Comment			
Corrective Action			Date:
Type: Plunger Lift	# 11	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Plunger Lift	# 11	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:

**Facilities:**  New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST	39.491632,-107.850643
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

**Venting:**

Yes/No	YES
Comment	Bradenhead valves open

**Flaring:**

Type	Satisfactory/Action Required		
Comment:			
Corrective Action:			Correct Action Date:

**Predrill**

Location ID: 298068  
 Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
**S/AR:** \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_  
**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_  
**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 298067 Type: WELL API Number: 045-17050 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298068 Type: WELL API Number: 045-17052 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298069 Type: WELL API Number: 045-17053 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298070 Type: WELL API Number: 045-17054 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298071 Type: WELL API Number: 045-17055 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298072 Type: WELL API Number: 045-17056 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298073 Type: WELL API Number: 045-17057 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298074 Type: WELL API Number: 045-17058 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298075 Type: WELL API Number: 045-17059 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298076 Type: WELL API Number: 045-17060 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

Facility ID: 298077 Type: WELL API Number: 045-17061 Status: PR Insp. Status: PR

**Producing Well**

Comment: **Plunger lift**

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Inspector Name: Murray, Richard

Emission Control Burner (ECB):  N

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels):  YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed?  Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite?  Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed?  Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Murray, Richard

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
 Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
 Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
 Gravel removed \_\_\_\_\_  
 Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
 Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
 Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
 Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_  
 Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Seeding	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: \_\_\_\_\_  
 Y  
 Comment: \_\_\_\_\_  
 CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT