

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2016

Document Number:

680701887

Overall Inspection:

SATISFACTORY w/ CMT  
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	256230	330883	Peterson, Tom	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspection@pdce.com	All inspections

**Compliance Summary:**QtrQtr: SENE Sec: 25 Twp: 4N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/13/2012	661601104	PR	PR	SATISFACTORY			No
01/22/2007	200103127	SR	PR	SATISFACTORY		Pass	No
01/21/2007	200103022	PR	PR	SATISFACTORY		Pass	No
03/04/2002	200024741	PR	PR	SATISFACTORY		Pass	No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
256230	WELL	PR	11/01/2007	OW	123-19820	FRANK 25-42	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Lease Road:</b>				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	ACTION REQUIRED	Landowner is storing equipment immediately adjacent to crude oil tank berm and within 20' of crude oil tank. See attached photo.	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "	08/12/2016

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
IGNITOR/COMBUST OR	SATISFACTORY	Panel		
SEPARATOR	SATISFACTORY	Livestock fencing		
TANK BATTERY	SATISFACTORY	Livestock fencing		
WELLHEAD	SATISFACTORY	Panel		

Equipment:				
Type: Plunger Lift	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment	N40.28593 W-104.83238			
Corrective Action				Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required:	SATISFACTORY	
Comment				
Corrective Action				Date:

Inspector Name: Peterson, Tom

Type: Emission Control Device	# 1	Satisfactory/Action Required: SATISFACTORY
Comment N40.28599 W-104.83235		
Corrective Action	Date:	
Type: Bird Protectors	# 2	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date:	

<b>Facilities:</b>	<input type="checkbox"/> New Tank	Tank ID: _____
Contents	#	Capacity
PRODUCED WATER	1	100 BBLS
Type	PBV FIBERGLASS	
SE GPS	40.285630,-104.832500	
S/AR	SATISFACTORY	Comment:
Corrective Action:	Corrective Date:	

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action	Corrective Date			
Comment	Shared berm with NEI API #123-16537			

<b>Facilities:</b>	<input type="checkbox"/> New Tank	Tank ID: _____
Contents	#	Capacity
CRUDE OIL	1	300 BBLS
Type	STEEL AST	
SE GPS	40.285630,-104.832500	
S/AR	SATISFACTORY	Comment:
Corrective Action:	Corrective Date:	

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action	Corrective Date			
Comment	Shared berm with NEI API #123-16537			

<b>Venting:</b>
Yes/No
NO
Comment

**Flaring:**

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:		Correct Action Date:

**Predrill**

Location ID: 256230

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 256230 Type: WELL API Number: 123-19820 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Inspector Name: Peterson, Tom

**BradenHead**

Comment: Bradenhead is exposed at surface.

CA:

CA Date:

**Environmental**

**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB): Y

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed? Pass

CM

CA CA Date

Unused or unneeded equipment onsite? Pass

CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass

CM

CA CA Date

Guy line anchors marked?

CM

CA CA Date

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

Inspector Name: Peterson, Tom

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_  
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_  
RESTORATION AND REVEGETATION  
Cropland  
Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_  
Non-Cropland  
Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_  
1003 f. Weeds Noxious weeds? \_\_\_\_\_  
Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_  
Final Land Use: \_\_\_\_\_  
Reminder: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_  
Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: \_\_\_\_\_  
CA: \_\_\_\_\_

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images ([https://cogcc.state.co.us/weblink/](https://cogcc.state.co.us/webblink/)) and search by document number:

Inspector Name: Peterson, Tom

Document Num	Description	URL
680701887	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3854495">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3854495</a>
680701888	Unused equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3854478">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3854478</a>