

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/12/2016
Document Number:
680300745
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|--------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>425407</u> | <u>425398</u> | <u>SCHURE, KYM</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 200149
 Name of Operator: ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLC
 Address: 3500 MASSILLON ROAD #100
 City: UNIONTOWN State: OH Zip: 44685

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-----------------------------|---------|
| Lueth, Broc | | blueth@enerjexresources.com | |

Compliance Summary:

QtrQtr: NENE Sec: 31 Twp: 8N Range: 43W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 03/22/2013 | 664000880 | PR | PR | SATISFACTORY | P | | No |

Inspector Comment:

Routine Site Inspection

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|--|
| 425407 | WELL | PR | 10/24/2012 | GW | 095-06358 | SCHLACHTER 843-31-41 | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

Special Purpose Pits: Drilling Pits: 1 Wells: 1 Production Pits:
 Condensate Tanks: Water Tanks: Separators: 1 Electric Motors:
 Gas or Diesel Mortors: 1 Cavity Pumps: LACT Unit: Pump Jacks: 1
 Electric Generators: Gas Pipeline: 1 Oil Pipeline: Water Pipeline: 1
 Gas Compressors: VOC Combustor: Oil Tanks: Dehydrator Units:
 Multi-Well Pits: Piggig Station: Flare: Fuel Tanks:

Location

| Lease Road: | | | | |
|--------------------|------------------------------|---------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| Access | SATISFACTORY | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
| | | | | |

Multiple Spills and Releases?

| Fencing/: | | | | |
|------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

Equipment:

| | | | | |
|---------------------|---|-------------------------------|--------------|-------|
| Type: Gas Meter Run | # 1 | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | | | | |
| Corrective Action | | | | Date: |
| Type: Prime Mover | # 1 | Satisfactory/Action Required: | SATISFACTORY | |
| Comment | Flowing - Hydraulic displacement insert - NG Engine | | | |
| Corrective Action | | | | Date: |

Venting:

| | |
|---------|--|
| Yes/No | |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 425407

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 425407 Type: WELL API Number: 095-06358 Status: PR Insp. Status: PR

Producing Well

Comment: **Flowing GW**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

| | | |
|------------------------|-------------------|-------------|
| Water Well: | Lat | Long |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ |

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Other | Pass | | | |

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: Use BMP's for stormwater erosion control and management

CA: _____

Pits: NO SURFACE INDICATION OF PIT