

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/13/2016

Document Number:

673901661

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |             |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       | 2A Doc Num: |
|                     | 202575      | 320086 | MONTOYA, JOHN   | <input type="checkbox"/> |             |

**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS LLCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone        | Email                     | Comment         |
|--------------|--------------|---------------------------|-----------------|
| Carlisle, J  | 970-534-6006 | jcarlile@extractionog.com | ALL INSPECTIONS |

**Compliance Summary:**QtrQtr: SWNE Sec: 9 Twp: 1S Range: 65W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 07/11/2013 | 668300515 | PR         | SI          | ACTION REQUIRED               | P        |                | No              |
| 06/06/2013 | 668300329 | PR         | SI          | ACTION REQUIRED               | P        |                | No              |
| 04/11/2013 | 668300029 | PR         | SI          | ACTION REQUIRED               | P        |                | No              |
| 11/25/2005 | 200080666 | PR         | PR          | ACTION REQUIRED               |          | Fail           | No              |
| 10/25/1999 | 893998    | PR         | PR          | SATISFACTORY                  |          | Pass           | No              |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|-------------------------------------|
| 202575      | WELL | PR     | 11/30/2007  | GW         | 001-07980 | KALLSEN 32-9 2 | PR          | <input checked="" type="checkbox"/> |

**Equipment:**Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

Inspector Name: MONTOYA, JOHN

|                    |                              |         |                   |      |
|--------------------|------------------------------|---------|-------------------|------|
| <b>Lease Road:</b> |                              |         |                   |      |
| Type               | Satisfactory/Action Required | comment | Corrective Action | Date |
| Main               | SATISFACTORY                 |         |                   |      |

|                      |                              |         |                   |         |
|----------------------|------------------------------|---------|-------------------|---------|
| <b>Signs/Marker:</b> |                              |         |                   |         |
| Type                 | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD             | SATISFACTORY                 |         |                   |         |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

|                           |                              |         |                   |         |
|---------------------------|------------------------------|---------|-------------------|---------|
| <b>Good Housekeeping:</b> |                              |         |                   |         |
| Type                      | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|                           |                              |         |                   |         |

|  |      |        |                   |         |
|--|------|--------|-------------------|---------|
| <b>Spills:</b>   |      |        |                   |         |
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

|                  |                              |   |                   |         |
|------------------|------------------------------|---|-------------------|---------|
| <b>Fencing/:</b> |                              |   |                   |         |
| Type             | Satisfactory/Action Required | Comment   | Corrective Action | CA Date |
| WELLHEAD         | SATISFACTORY                 | BARBWIRE<br>FENCESE<br>CORNERN39.58935<br>W-104.39922 |                   |         |

|                    |     |  |  |       |
|--------------------|-----|--|--|-------|
| <b>Equipment:</b>  |     |  |  |       |
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: SATISFACTORY |  |       |
| Comment            |     |  |  |       |
| Corrective Action  |     |  |  | Date: |

|                 |  |
|-----------------|--|
| <b>Venting:</b> |  |
| Yes/No          |  |
| Comment         |  |

|                    |                              |                      |  |
|--------------------|------------------------------|----------------------|--|
| <b>Flaring:</b>    |                              |                      |  |
| Type               | Satisfactory/Action Required |                      |  |
| Comment:           |                              |                      |  |
| Corrective Action: |                              | Correct Action Date: |  |

**Predrill**

Location ID: 202575

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 202575 Type: WELL API Number: 001-07980 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: BRADENHEAD PLUMBED TO SURFACE

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: MONTOYA, JOHN

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

**Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

**Non-Cropland**

Inspector Name: MONTOYA, JOHN

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| INTERMITTER CONTROLLER ON WELLHEAD, DOCUMENT @668300515, DSTED 7/11/13, TRASH AND UNUSED EQUIPMENT PICKEDUP,WEEDS HAVE BEEN CONTROLLED, SOIL AT TANKS HAVE BEEN REMEDIATED, DEADMEN MARKED | montoyaj | 05/13/2016 |