

CEMENT JOB REPORT



CUSTOMER BAYSWATER EXPLORATION ;			DATE 30-JAN-16		F.R. # 10011191189		SERV. SUPV. FELIPE LANDA								
LEASE & WELL NAME Albrighton H-10HC - API 05123424940000			LOCATION 10-6N-64W			COUNTY-PARISH-BLOCK Weld Colorado									
DISTRICT Brighton			DRILLING CONTRACTOR RIG # Frontier 8			TYPE OF JOB Surface									
SIZE & TYPE OF PLUGS		LIST-CSG-HARDWARE			MECHANICAL BARRIERS		MD	TVD	HANGER TYPES		MD	TVD			
9-5/8" Top Cem Plug, Nitrile cvr, Phc		Cement Basket, Slip On, 9-5/8 in													
		Float Collar, Al Flap, 9-5/8 - 8rd													
		Float Shoe 9-5/8 - 8rd													
MATERIALS FURNISHED BY BJ				LAB REPORT NO.				PHYSICAL SLURRY PROPERTIES							
								SACKS OF CEMENT	SLURRY WGT PPG	SLURRY YLD FT3	WATER GPS	PUMP TIME HR:MIN	Bbl SLURRY	Bbl MIX WATER	
Fresh Water									8.34				20		
Type III Cement + Adds								695	14.5	1.40	6.79		172.89	112.34	
Fresh Water									8.34				116.1		
Available Mix Water		400 Bbl.		Available Displ. Fluid		400 Bbl.		TOTAL				308.99	112.34		
HOLE			TBG-CSG-D.P.						COLLAR DEPTHS						
SIZE	% EXCESS	DEPTH	ID	OD	WGT.	TYPE	MD	TVD	GRADE	SHOE	FLOAT	STAGE			
13.5	30	1560	8.921	9.625	36	CSG	1548	1500		1548	1503				
LAST CASING			PKR-CMT RET-BR PL-LINER				PERF. DEPTH		TOP CONN		WELL FLUID				
ID	OD	WGT	TYPE	MD	TVD	BRAND & TYPE		DEPTH	TOP	BTM	SIZE	THREAD	TYPE	WGT.	
						NO PACKER		0			9.625	8RD	WATER BASED	8.34	
DISPL. VOLUME		DISPL. FLUID		CAL. PSI	CAL. MAX PSI	OP. MAX	MAX TBG PSI		MAX CSG PSI		MIX WATER				
VOLUME	UOM	TYPE		WGT.	BUMP PLUG	TO REV.	SQ. PSI	RATED	Operator	RATED	Operator				
116.1	BBLS	Fresh Water		8.34	481	0	0	0	0	3950	3160	TANK			
Circulation Prior to Job															
Circulated Well: Rig <input checked="" type="checkbox"/> BJ <input type="checkbox"/>				Circulation Time: 1				Circulation Rate: 6.5 BPM							
Mud Density In: 8.9 LBS/GAL				Mud Density Out: 8.9 LBS/GAL				PV & YP Mud In:				PV & YP Mud Out:			
Gas Present: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>				Units:				Solids Present at End of Circulation: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>							
Displacement And Mud Removal															
Displaced By: Rig <input type="checkbox"/> BJ <input checked="" type="checkbox"/>				Amount Bled Back After Job: 1.5 BBLS											
Returns During Job: <input type="checkbox"/> NONE <input type="checkbox"/> PARTIAL <input checked="" type="checkbox"/> FULL				Method Used to Verify Returns: VISUAL											
Cement Returns at Surface: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO				Were Returns Planned at Surface: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES											
Pipe Movement: <input type="checkbox"/> ROTATION <input type="checkbox"/> RECIPROCATION <input type="checkbox"/> NONE <input type="checkbox"/> UNABLE DUE TO STUCK PIPE															
Centralizers: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES				Quantity: 15				Type: <input type="checkbox"/> BOW <input type="checkbox"/> RIGID							
Job Pumped Through: <input type="checkbox"/> CHOKE MANIFOLD <input type="checkbox"/> SQUEEZE MANIFOLD <input checked="" type="checkbox"/> MANIFOLD <input type="checkbox"/> NO MANIFOLD															
Plugs															
Number of Attempts by BJ: 0				Competition:				Wiper Balls Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES Quantity:							
Plug Catcher Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Parabow Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES											
Was There a Bottom: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Top of Plug: 0 FT				Bottom of Plug: 0 FT							
Squeezes (Update Original Treatment Report for Primary Job)															
BLOCK SQUEEZE <input type="checkbox"/>				SHOE SQUEEZE <input type="checkbox"/>				TOP OF LINER SQUEEZE <input type="checkbox"/>				PLANNED <input type="checkbox"/> UNPLANNED <input type="checkbox"/>			
Liner Packer: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				Bond Log: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES				PSI Applied: 0				Fluid Weight: 0 LBS/GAL			
Casing Test (Update Original Treatment Report for Primary Job)															
Casing Test Pressure: 0 PSI				With 0 LBS/GAL Mud				Time Held: 00 Hours 00 Minutes							
EXPLANATION: TROUBLE SETTING TOOL, RUNNING CSG, ETC. PRIOR TO CEMENTING:															
PRESSURE/RATE DETAIL										EXPLANATION					

CEMENT JOB REPORT



Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT	Target EMW: 0 LBS/GAL	Actual EMW: 0 LBS/GAL
Number of Times Tests Conducted: 0	Mud Weight When Test was Conducted: 0 LBS/GAL	

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)
NONE

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)
NONE

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)
NONE

PRESSURE/RATE DETAIL						EXPLANATION	
TIME HR.:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>	
	PIPE	ANNULUS				TEST LINES	3806 PSI
						CIRCULATING WELL - RIG <input checked="" type="checkbox"/> BJ <input type="checkbox"/>	
00:15	0	0	0	0	NA	ARRIVE ON LOCATION (rig running casing)	
01:00	0	0	0	0	NA	BHI STANDING BY (rig running casing)	
02:30	0	0	0	0	NA	SPOT TRUCKS/PRE RIG UP SAFETY MEETING	
03:00	0	0	0	0	NA	PRE JOB SAFETY MEETING	
03:15	0	0	.8	1	H2O	LOAD LINES	
03:17	3806	0	0	0	H2O	PRESSURE TEST	
03:20	93	0	4.8	10	H2O	FRESH WATER	
03:24	101	0	4.8	10	H2O	FRESH WATER + DYE	
03:30	205	0	4.2	169	CEMENT	695 SACKS OF TYPE III CEMENT + 0.08 lbs/sack STATIC FREE + 0.5% CALCIUM CHLORIDE + 0.25 lbs/sack CELLO FLAKE + 0.01 gps FP-6L @ 14.5 PPG	
04:25	0	0	0	0	NA	DROP PLUG	
04:26	501	0	70	6	H2O	DISPLACE	
04:38	621	0	30	4.8	H2O	RATE CHANGE	
04:45	628	0	16	3.6	H2O	RATE CHANGE	
04:48	1201	0	0	3.6	H2O	BUMP PLUG @ (30 bbls of cement to surface)	
04:53	0	0	0	0	H2O	CHECK FLOATS	
05:00	0	0	0	0	NA	POST JOB RIG DOWN SAFETY MEETING	

BUMPED PLUG	PSI TO BUMP PLUG	TEST FLOAT EQUIP.	BBL.CMT RETURNS/ REVERSED	TOTAL BBL. PUMPED	PSI LEFT ON CSG	SPOT TOP OUT CEMENT	Service Supervisor Signature:
<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	1201	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	30	305	0	Y <input checked="" type="checkbox"/> N	

