

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401049845

Date Received:

05/18/2016

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

445470

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: <u>SYNERGY RESOURCES CORPORATION</u>	Operator No: <u>10311</u>	<b>Phone Numbers</b>
Address: <u>20203 HIGHWAY 60</u>		Phone: <u>(970) 7371073</u>
City: <u>PLATTEVILLE</u>	State: <u>CO</u>	Mobile: <u>(970) 2300435</u>
Zip: <u>80651</u>		Email: <u>dpennington@syrginfo.com</u>
Contact Person: <u>David Pennington</u>		

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401026931

Initial Report Date: 04/13/2016 Date of Discovery: 04/12/2016 Spill Type: Historical Release

#### Spill/Release Point Location:

Location of Spill/Release: QTRQTR NENW SEC 12 TWP 6N RNG 65W MERIDIAN 6

Latitude: 40.507591 Longitude: -104.609899

Municipality (if within municipal boundaries): \_\_\_\_\_ County: WELD

#### Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 323590

☐ No Existing Facility or Location ID No.

☐ Well API No. (Only if the reference facility is well) 05- -

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

#### Land Use:

Current Land Use: CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Clear 70s

Surface Owner: FEE

Other(Specify): \_\_\_\_\_

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☒ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

*As defined in COGCC 100-Series Rules*

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Historical hydrocarbon impacts to soil and groundwater were observed while removing a buried concrete vault as part of P&A activities. Synergy is presently conducting source removal excavations in and around the area of discovery. The associated well, flow line, and processing equipment have already been decommissioned and removed from the Site.

List Agencies and Other Parties Notified:

### OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
4/13/2016	Weld County LGD	Troy Swain	970-3536100	No Response

### SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 05/18/2016		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE			<input checked="" type="checkbox"/>
PRODUCED WATER			<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls &amp; floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input checked="" type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>50</u>		Width of Impact (feet): <u>50</u>	
Depth of Impact (feet BGS): <u>8</u>		Depth of Impact (inches BGS): <u>96</u>	
How was extent determined?			
Confirmation soil and groundwater samples collected from the source removal excavation and from soil borings and groundwater monitoring wells installed to delineate the extent of the impacts.			
Soil/Geology Description:			
Otero Sandy Loam, 1-3% slope			
Depth to Groundwater (feet BGS) <u>8</u>		Number Water Wells within 1/2 mile radius: <u>6</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>355</u> None <input type="checkbox"/>	Surface Water <u>90</u> None <input type="checkbox"/>	
	Wetlands <u></u> None <input checked="" type="checkbox"/>	Springs <u></u> None <input checked="" type="checkbox"/>	
	Livestock <u></u> None <input checked="" type="checkbox"/>	Occupied Building <u>280</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			

### CORRECTIVE ACTIONS

#1 Supplemental Report Date: 05/18/2016

Cause of Spill (Check all that apply) ☐ Human Error ☐ Equipment Failure ☒ Historical-Unknown  
☐ Other (specify) \_\_\_\_\_

Describe Incident & Root Cause (include specific equipment and point of failure)

A Synergy representative observed historical impacts to soil and groundwater while conducting plug and abandonment activities at the Site.

Describe measures taken to prevent the problem(s) from reoccurring:

The facility is presently being plugged and abandoned.

Volume of Soil Excavated (cubic yards): 850

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment  
☐ Other (specify) \_\_\_\_\_

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)  
☐ Work proceeding under an approved Form 27  
Form 27 Remediation Project No: \_\_\_\_\_

### OPERATOR COMMENTS:

LTE, on behalf of Synergy, will be submitting a Form 27 Site Investigation and Remediation Workplan within 90 days of this Supplemental Form 19.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Jess Alexander  
Title: Proj. Env. Scientist Date: 05/18/2016 Email: jalexander@ltenv.com

<u>COA Type</u>	<u>Description</u>

## Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>

Total Attach: 0 Files

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)