



Photo#1: View of Location to North; showing Pit excavation.

May 12, 2016

Inspection Photos: Culverwell API#081-07364



Photo#2: View to South; showing Access Road entry to Location.

Inspection Photos: Culverwell API#081-07364

May 12, 2016



Photo#3: View to East of Fill Slope Area.

Inspection Photos: Culverwell API#081-07364

May 12, 2016



Photo#4: Fill Slope at South side of Location.

Inspection Photos: Culverwell API#081-07364

May 12, 2016



Photo#5: Volunteer Vegetation on Location.

Inspection Photos: Culverwell API#081-07364

May 12, 2016