

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
05/24/2016
Document Number:
673901830
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	201947	319938	MONTOYA, JOHN	2A Doc Num:	

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Compliance Summary:

QtrQtr: NESW Sec: 29 Twp: 1S Range: 64W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/25/2008	200129093	PR	PR	SATISFACTORY			No
06/23/2004	200056046	PR		SATISFACTORY		Pass	No
05/12/2004	200054296	PR	PR	ACTION REQUIRED		Fail	Yes
06/26/1998	500132019	PR	PR			Fail	Yes

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201947	WELL	PR	01/11/1979	GW	001-07351	UPRR 23 PAN AM D 3	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY			

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	2" PIPE FENCESE CORNERN39.55994 W-104.34601		

Equipment:				
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:
Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:
Type: Bird Protectors	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:
Type: Plunger Lift	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action				Date:

Facilities:				
<input type="checkbox"/> New Tank	Tank ID: _____			
Contents	#	Capacity	Type	SE GPS

CRUDE OIL	1	300 BBLs	STEEL AST	39.560030,-104.345460
-----------	---	----------	-----------	-----------------------

S/AR	SATISFACTORY	Comment:	
------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Facilities:

New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLs	CONCRETE SUMP/VAULT	,

S/AR	SATISFACTORY	Comment:	50 BBLs CAPACITY CONCRETE VAULT
------	--------------	----------	---------------------------------

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:

Yes/No	
--------	--

Comment	
---------	--

Flaring:

Type		Satisfactory/Action Required	
------	--	------------------------------	--

Comment:

Corrective Action:		Correct Action Date:	
--------------------	--	----------------------	--

Predrill

Location ID: 201947

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 201947 Type: WELL API Number: 001-07351 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

CA: _____

CA Date: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION
Cropland
 Top soil replaced _____ Recontoured _____ Perennial forage re-established _____
Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____
 1003 f. Weeds Noxious weeds? _____
 Comment: _____
 Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:
 Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____
 Final Land Use: _____
 Reminder: _____
 Comment: _____
 Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment: _____
 Corrective Action: _____ Date _____
 Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR _____ Corrective Date: _____
 Y _____
 Comment: _____
 CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments		
Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD	montoyaj	05/24/2016