

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2016

Document Number:

673901867

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	421677	318744	MONTOYA, JOHN	2A Doc Num:	

Operator Information:

OGCC Operator Number:	<u>47120</u>
Name of Operator:	<u>KERR MCGEE OIL & GAS ONSHORE LP</u>
Address:	<u>P O BOX 173779</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections
REDDY, LUKE		Luke.Reddy@anadarko.com	ALL INSPECTIONS
Avant, Paul	720-929-6475	Paul.Avant@anadarko.com	regulatory

Compliance Summary:

QtrQtr:	<u>NWNW</u>	Sec:	<u>15</u>	Twp:	<u>2N</u>	Range:	<u>65W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/27/2012	667600987	PR	SI	SATISFACTORY	I		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
242083	WELL	PA	08/14/2013	SI	123-09874	UPRR 62 PAN AM GAS UNIT K 2	PA	<input checked="" type="checkbox"/>
421674	WELL	PR	08/04/2011	OW	123-33005	THOMASON 5-15	PR	<input checked="" type="checkbox"/>
421675	WELL	PR	08/04/2011	OW	123-33006	THOMASON 32-15	PR	<input checked="" type="checkbox"/>
421677	WELL	PR	08/04/2011	OW	123-33008	THOMASON 25-15	PR	<input checked="" type="checkbox"/>
421686	WELL	PR	07/12/2011	OW	123-33015	THOMASON 4-15	PR	<input checked="" type="checkbox"/>
421687	WELL	PR	08/05/2011	OW	123-33016	THOMASON 31-15	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>6</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>2</u>	Separators: <u>8</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>8</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	5 ROD IRON FENCES ON 5 WELLSSE CORNERN40.08587 W-104.39353		

Equipment:

Type: Plunger Lift	# 5	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action	Date:	

Venting:

Yes/No	
Comment	

Flaring:

Type	Satisfactory/Action Required
Comment:	

Corrective Action: _____	Correct Action Date: _____
--------------------------	----------------------------

Predrill

Location ID: 421677
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____
 Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:
 Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:
 Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____
LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 242083 Type: WELL API Number: 123-09874 Status: PA Insp. Status: PA

Facility ID: 421674 Type: WELL API Number: 123-33005 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE
 CA: _____
 CA Date: _____

Facility ID: 421675 Type: WELL API Number: 123-33006 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

CA:

CA Date:

Facility ID: 421677 Type: WELL API Number: 123-33008 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

CA:

CA Date:

Facility ID: 421686 Type: WELL API Number: 123-33015 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

CA:

CA Date:

Facility ID: 421687 Type: WELL API Number: 123-33016 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: BRADENHEAD PLUMBED TO SURFACE

CA:

CA Date:

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____
 Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment: _____
 Corrective Action: _____ Date _____
 Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____
 Comment: _____
 CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments		
Comment	User	Date
5 INTERMITTER CONTROLLERS ON 5 WELLHEADS	montoyaj	05/27/2016