



**photo 1:** Facing west toward the cement pad (1) at Lat/Long: 40.08697,-103.68970.



**photo 2:** Facing southeast toward the cement pad (1) at Lat/Long: 40.08697,-103.68970.



**photo 3:** Facing northeast at the location. Various metal and wood debris was scattered throughout the location.



**photo 4:** Cement pad (2) found at 40.08653,-103.69091.



**photo 5:** Facing west toward cement pad (3) found at Lat/Long:40.08641,-103.69047.



**photo 6:** Facing west, work began with breaking apart cement pads.