

**Photo#1:**  
View North over Location ;



**Photo#2:**  
View South over Location.



Photo#3:

View East over Location



Photo#4:

View West over Location





Photo#5: Successful establishment of Perennial Vegetation

May 12, 2016

Inspection Photos: COGCC Gerber API# 081-07359



Photo#6: There are still areas of concern that will benefit from Monitoring

May 12, 2016

Inspection Photos: COGCC Gerber API# 081-07359