

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2016

Document Number:

675202877

Overall Inspection:

SATISFACTORY w/ CMT
or AR

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>334404</u>	<u>334404</u>	<u>CONKLIN, CURTIS</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10433</u>
Name of Operator:	<u>LARAMIE ENERGY LLC</u>
Address:	<u>1401 SEVENTEENTH STREET #1400</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor

Compliance Summary:

QtrQtr: SWSW Sec: 11 Twp: 10S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/26/2016	675202449			SATISFACTORY			No
07/13/2015	675201770			SATISFACTORY		Pass	No
07/13/2015	675201771			SATISFACTORY			No
02/10/2015	675201188			ACTION REQUIRED			No

Inspector Comment:

Inspection in response to Flash Flood incident on 5/27/16. Wells were shut in and tanks drained on 5/26/16. No access to location at time of inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
299393	WELL	PR	08/31/2012	GW	077-09807	HAWKINS RANCH 14-3A	SI	<input checked="" type="checkbox"/>
300181	WELL	PR	12/20/2010	GW	077-09886	HAWKINS RANCH 14-4A	SI	<input checked="" type="checkbox"/>
300182	WELL	PR	10/24/2010	GW	077-09885	HAWKINS RANCH 11-13C	SI	<input checked="" type="checkbox"/>
300183	WELL	AL	10/24/2012	LO	077-09884	HAWKINS RANCH 10-16C	AL	<input type="checkbox"/>
300184	WELL	AL	06/28/2011	LO	077-09883	HAWKINS RANCH 15-1A	AL	<input type="checkbox"/>
300185	WELL	AL	10/24/2012	LO	077-09882	HAWKINS RANCH 10-16B	AL	<input type="checkbox"/>
301700	WELL	AL	12/06/2012	LO	077-10012	Hawkins Ranch 10-9B	AL	<input type="checkbox"/>

301702	WELL	AL	12/03/2012	LO	077-10014	Hawkins Ranch 10-9C	AL	<input type="checkbox"/>
301704	WELL	AL	12/03/2012	LO	077-10016	Hawkins Ranch 10-10B	AL	<input type="checkbox"/>
301705	WELL	AL	12/07/2012	LO	077-10017	Hawkins Ranch 11-13B	AL	<input type="checkbox"/>
301706	WELL	AL	12/07/2012	LO	077-10018	Hawkins Ranch 11-14A	AL	<input type="checkbox"/>
301707	WELL	AL	12/06/2012	LO	077-10019	Hawkins Ranch 11-13A	AL	<input type="checkbox"/>
301708	WELL	AL	12/07/2012	LO	077-10020	Hawkins Ranch 11-13	AL	<input type="checkbox"/>
301710	WELL	AL	12/06/2012	LO	077-10022	Hawkins Ranch 10-15C	AL	<input type="checkbox"/>
301711	WELL	AL	12/06/2012	LO	077-10023	Hawkins Ranch 10-16	AL	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:			Correct Action Date:

Predrill

Location ID: 334404

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 299393 Type: WELL API Number: 077-09807 Status: PR Insp. Status: SI

Facility ID: 300181 Type: WELL API Number: 077-09886 Status: PR Insp. Status: SI

Facility ID: 300182 Type: WELL API Number: 077-09885 Status: PR Insp. Status: SI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: CONKLIN, CURTIS

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

Comment:

Corrective Action: Date

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

S/A/V: Corrective Date:

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
COGCC staff will do a follow up inspection once access is restored and pad clean has begun.	conklinc	05/31/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675202877	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3868174