

Final Reclamation Inspection- Bond Release



Photo 1. Photo taken of PR well sign for API 123-22392.

Final Reclamation Inspection- Bond Release



Photo 2. Photo taken of PR well sign for API 123-22402.

Final Reclamation Inspection- Bond Release



Photo 3. Photo taken from west of location, facing East. This is a well release on an active, multi-well location. Noble Energy did not construct the location; Kerr McGee did the construction at the location.

Final Reclamation Inspection- Bond Release



Photo 4. Aerial imagery from 09/2015 using COGCC GISOnline, illustrating the two (2) active wells of Kerr McGee, not Noble Energy.