

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2016

Document Number:

674702767

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335722	335722	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 53650Name of Operator: MARATHON OIL COMPANYAddress: 1501 STAMPEDE AVENUECity: CODY State: WY Zip: 82414

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Stebbins, Tiffany	307-527-2223	tastebbins@marathonoil.com	Regulatory Compli Rep (Wyoming)

Compliance Summary:QtrQtr: NESE Sec: 1 Twp: 6S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/01/2015	674701197			SATISFACTORY			No
07/31/2014	674700158			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
291567	WELL	PR	02/02/2008	GW	045-14442	CHEVRON-MARATHON 13A-6D	PR	<input checked="" type="checkbox"/>
291571	WELL	PR	01/22/2008	GW	045-14443	CHEVRON-MARATHON 42D-1D	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: 866-662-2378

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Equipment:				
Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		
Type: Bird Protectors	# 2	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		
Type: Plunger Lift	# 2	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		
Type: Horizontal Heated Separator	# 2	Satisfactory/Action Required: SATISFACTORY		
Comment				
Corrective Action		Date: _____		

Facilities: <input type="checkbox"/> New Tank Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST	,

Inspector Name: LONGWORTH, MIKE

S/AR	SATISFACTORY	Comment:	Airid 045-1677-001			
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition		Adequate				
Other (Content) _____						
Other (Capacity) _____						
Other (Type) _____						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Corrective Action					Corrective Date	
Comment						
Facilities: <input type="checkbox"/> New Tank Tank ID: _____						
Contents	#	Capacity	Type	SE GPS		
PRODUCED WATER	1	400 BBLS	STEEL AST	,		
S/AR	SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition		Adequate				
Other (Content) _____						
Other (Capacity) _____						
Other (Type) _____						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Corrective Action					Corrective Date	
Comment						
Facilities: <input type="checkbox"/> New Tank Tank ID: _____						
Contents	#	Capacity	Type	SE GPS		
CONDENSATE	1	400 BBLS	STEEL AST	,		
S/AR	SATISFACTORY	Comment:	Air id 045-1677-001			
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition		Adequate				
Other (Content) _____						
Other (Capacity) _____						
Other (Type) _____						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Corrective Action					Corrective Date	

Comment				
Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
METHANOL	1	<50 BBLS	STEEL AST	,
S/AR	SATISFACTORY		Comment:	
Corrective Action:				Corrective Date:
Paint				
Condition	Adequate			
Other (Content) _____				
Other (Capacity) 500 gallons				
Other (Type) _____				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				
Venting:				
Yes/No	NO			
Comment				
Flaring:				
Type		Satisfactory/Action Required		
Comment:				
Corrective Action:				Correct Action Date:

Predrill

Location ID: 335722

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 291567 Type: WELL API Number: 045-14442 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 291571 Type: WELL API Number: 045-14443 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Inspector Name: LONGWORTH, MIKE

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
DWR Receipt Num: _____		Owner Name: _____	GPS : _____
Field Parameters:			
Sample Location: _____			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____		Wildlife Protection Devices (fired vessels): _____	
Reclamation - Storm Water - Pit			
Interim Reclamation:			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: _____			
1003a. Waste and Debris removed? <u>Pass</u>			
CM _____			
CA _____		CA Date _____	
Unused or unneeded equipment onsite? <u>Pass</u>			
CM _____			
CA _____		CA Date _____	
Pit, cellars, rat holes and other bores closed? _____			
CM _____			
CA _____		CA Date _____	
Guy line anchors marked? _____			
CM _____			
CA _____		CA Date _____	
1003b. Area no longer in use? _____		Production areas stabilized ? _____	
1003c. Compacted areas have been cross ripped? _____			
1003d. Drilling pit closed? _____		Subsidence over on drill pit? _____	
Cuttings management: _____			
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____			
Production areas have been stabilized? _____		Segregated soils have been replaced? _____	
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
Top soil replaced _____		Recontoured _____	Perennial forage re-established _____
<u>Non-Cropland</u>			

Inspector Name: LONGWORTH, MIKE

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
		Gravel	Pass			
		Check Dams	Pass			
Seeding	Pass					
Gravel	Pass					
Compaction	Pass					
		Compaction	Pass			
		Culverts	Pass			

S/A/V: SATISFACTOR

Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT