

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/02/2016
Document Number:
666802212
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>210493</u>	<u>335570</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>PO BOX 370</u>
City:	<u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

Compliance Summary:

QtrQtr: SWNE Sec: 16 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/17/2010	200237515	PR	PR	SATISFACTORY			No
03/12/2008	200128204	PR	PR	SATISFACTORY			No
03/12/2008	200128203	PR	PR	SATISFACTORY			No
04/01/2006	200090974	PR	PR	SATISFACTORY		Pass	No
01/24/2000	200004896	PR	PR	SATISFACTORY		Pass	No
03/07/1997	500142063	PR	PR			Pass	No
01/02/1997	500142062	PR	PR				No

Inspector Comment:

Location has 2 Location IDs, Shared location 311629

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111327	PIT	CL	09/23/1999		-	CLOUGH 7	CL <input type="checkbox"/>
210493	WELL	PR	02/03/1981	GW	045-06249	CLOUGH 7	PR <input checked="" type="checkbox"/>
280011	WELL	PR	07/20/2006	GW	045-11146	CLOUGH RWF 331-16	PR <input checked="" type="checkbox"/>
280012	WELL	PR	07/20/2006	GW	045-11147	CLOUGH RWF 432-16	PR <input checked="" type="checkbox"/>
280013	WELL	PR	08/08/2006	GW	045-11148	CLOUGH RWF 533-16	PR <input checked="" type="checkbox"/>
280014	WELL	PR	08/08/2006	GW	045-11149	CLOUGH RWF 332-16	PR <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Predrill

Location ID: 210493
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 210493 Type: WELL API Number: 045-06249 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger Lift**

Facility ID: 280011 Type: WELL API Number: 045-11146 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger Lift**

Facility ID: 280012 Type: WELL API Number: 045-11147 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger Lift**

Facility ID: 280013 Type: WELL API Number: 045-11148 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger Lift**

Facility ID: 280014 Type: WELL API Number: 045-11149 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger Lift**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Slope Roughening	Pass					
		Culverts	Pass			
		Sediment Traps	Pass			
Ditches	Pass					
		Ditches	Pass			
Sediment Traps	Pass					

Inspector Name: Murray, Richard

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT