



Photo 1. View of tank that remains on location. Black oily substance is present on soil at base of tank.



Photo 2. View of oily material observed at the base of the tank.



Photo 3. View of pit facing westward. Surface owner indicated that pit has largely filled in so original size of pit is unknown. At this time the pit is approximately 20 feet long and 10 feet wide.



Photo 4. View of approximate well location facing northward. It appears that cuttings are present on the soil surface.



Photo 5. View of approximate well location facing southward.



Photo 6. View of approximate well location facing eastward.



Photo 7. View of approximate well location facing westward.