

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2016

Document Number:

681901018

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	317564	317564	HELGELAND, GARY	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		COGCCinspections@anadarko.com	All Inspections
Reddy, Luke		luke.reddy@anadarko.com	All Inspections

Compliance Summary:QtrQtr: SESW Sec: 21 Twp: 1N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/01/2016	682400600			SATISFACTORY		Pass	No
11/20/2015	681900218			ACTION REQUIRED	I		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
239461	WELL	PR	09/21/1998	GW	123-07248	UPRR 42 PAN AM B 1	PR	<input type="checkbox"/>
431801	WELL	AL	12/17/2014	LO	123-36784	HOWARD 29C-21HZ	AL	<input type="checkbox"/>
431802	WELL	AL	06/20/2013	LO	123-36785	HOWARD 28N-33HZ	AL	<input type="checkbox"/>
431803	WELL	AL	06/20/2013	LO	123-36786	HOWARD 29C-33HZ	AL	<input type="checkbox"/>
431804	WELL	PR	03/05/2014	OW	123-36787	HOWARD 4C-21HZ	PR	<input checked="" type="checkbox"/>
431805	WELL	AL	06/20/2013	LO	123-36788	HOWARD 30C-33HZ	AL	<input type="checkbox"/>
431806	WELL	DG	03/01/2015	LO	123-36789	HOWARD 4C-33HZ	DG	<input type="checkbox"/>
431807	WELL	AL	06/20/2013	LO	123-36790	HOWARD 29N-33HZ	AL	<input type="checkbox"/>

Inspector Name: HELGELAND, GARY

431808	WELL	AL	06/20/2013	LO	123-36791	HOWARD 4N-33HZ	AL	<input type="checkbox"/>
431809	WELL	PR	03/05/2014	OW	123-36792	HOWARD 29N-21HZ	PR	<input checked="" type="checkbox"/>
431810	WELL	AL	12/17/2014	LO	123-36793	HOWARD 4N-21HZ	AL	<input type="checkbox"/>
431811	WELL	PR	03/05/2014	OW	123-36794	HOWARD 29C-21HZ	PR	<input checked="" type="checkbox"/>
431812	WELL	PR	03/01/2016	OW	123-36795	HOWARD 30N-21HZX	PR	<input checked="" type="checkbox"/>
431813	WELL	AL	06/20/2013	LO	123-36796	HOWARD 3N-33HZ	AL	<input type="checkbox"/>
431814	WELL	PR	03/03/2014	OW	123-36797	HOWARD 3N-21HZ	PR	<input checked="" type="checkbox"/>
431815	WELL	AL	06/20/2013	LO	123-36798	HOWARD 3C-33HZ	AL	<input type="checkbox"/>
431835	WELL	PR	03/03/2014	OW	123-36809	HOWARD 28C-21HZ	PR	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>2</u>	Wells: <u>17</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>16</u>	Separators: <u>16</u>	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: <u>2</u>	Pump Jacks: <u>16</u>
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>16</u>	Oil Tanks: <u>64</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>16</u>	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Inspector Name: HELGELAND, GARY

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	Panel		

Equipment:

Type: Plunger Lift	# 6	Satisfactory/Action Required:	SATISFACTORY
Comment	Refer to inspection # 681901004 for information concerning shared battery and equipment.		
Corrective Action		Date:	

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 317564

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 431804 Type: WELL API Number: 123-36787 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA: _____

CA Date: _____

Facility ID: 431809 Type: WELL API Number: 123-36792 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA:

CA Date:

Facility ID: 431811 Type: WELL API Number: 123-36794 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA:

CA Date:

Facility ID: 431812 Type: WELL API Number: 123-36795 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA:

CA Date:

Facility ID: 431814 Type: WELL API Number: 123-36797 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA:

CA Date:

Facility ID: 431835 Type: WELL API Number: 123-36809 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA:

CA Date:

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): Y _____

Comment: _____

Pilot: ON _____

Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1003a. Waste and Debris removed? Pass _____

CM _____

CA _____

CA Date _____

Unused or unneeded equipment onsite? Pass _____

CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? Pass _____

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized ? Pass _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass _____

Recontoured Pass _____

80% Revegetation _____

In _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Inspector Name: HELGELAND, GARY

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681901018	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872270