



Photo#1: View NW over Location.

May 3, 2016

Inspection Photos: WPX Barrett AL API# 045-07033



Photo#2: View over Abandoned Facilities from SE to NW; Wells in background.

May 3, 2016

Inspection Photos: WPX Barrett AL API# 045-07033



Photo#3

Photo#4

Un-Reclaimed Facilities / Flow Lines





Photo#5:

Photo#6:

Un-Reclaimed Facilities



May 3, 2016

Inspection Photos: WPX Barrett AL API# 045-07033