

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2016

Document Number:

666802200

Overall Inspection:

**ACTION REQUIRED****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	210419	322404	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES, INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
O'Hare, Mickey		amohare@maralexinc.com	
Ellsworth, Stuart		stuart.ellsworth@state.co.us	

**Compliance Summary:**QtrQtr: SENW Sec: 17 Twp: 7S Range: 90W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/27/2013	670200600	SI	TA	ALLEGED VIOLATION			Yes
11/05/2009	200221963	CO	SI	ACTION REQUIRED			Yes
07/11/2007	200116908	PR	SI	SATISFACTORY	I		No
06/13/2007	200113018	ID	SI	SATISFACTORY	I	Pass	No
08/05/2003	200051339	CO	SI	SATISFACTORY	I	Fail	Yes
01/14/2003	200039127	PR	PR	SATISFACTORY		Pass	No
05/30/2000	200007687	ID	SI	SATISFACTORY		Pass	No
10/24/1996	500142014	ID	SI			Pass	No

**Inspector Comment:**

Action required items noted on previous inspection Document number 670200600 dated 06/27/2013 and NOAV document number 200382488 dated 07/02/2013 for items needed to maintain Shut-in or Temporarily Abandoned well status have not been satisfied. Action required items for close tank to atmosphere, remove unused equipment have not been satisfied.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111798	PIT		09/23/1999		-	BALDY CREEK 1-17	<input type="checkbox"/>
113530	PIT		09/23/1999		-	BALDY CREEK 1-7	<input type="checkbox"/>
210419	WELL	SI	04/27/2012	GW	045-06175	BALDY CREEK UNIT 1-17	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Inspector Name: Murray, Richard

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

#### Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

#### Equipment:

Type: Pump Jack	# 1	Satisfactory/Action Required:	ACTION REQUIRED
Comment	No prime mover, noted on previous inspection		
Corrective Action	remove unused equipment		Date: 7/12/2013
Type: Horizontal Heated Separator	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action			Date:
Type: Gas Meter Run	# 2	Satisfactory/Action Required:	SATISFACTORY
Comment			

Corrective Action	Date:
-------------------	-------

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST	39.446950,-107.468020

S/AR **ACTION REQUIRED** Comment: **Openings on top of tank not capped as noted on previous inspection, Lower port not plugged**

Corrective Action: **Close tank to atmosphere.** Corrective Date: **07/12/2013**

**Paint**

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
Comment	

**Venting:**

Yes/No	YES
Comment	<b>Bradenhead valve open, Produced water tank open to atmosphere</b>

**Flaring:**

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

**Predrill**

Location ID: 210419

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 210419 Type: WELL API Number: 045-06175 Status: SI Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

S/A/V: \_\_\_\_\_

CA Date: 07/12/2013

CA: Contact COGCC Area Engineer.

Comment: Last production numbers posted Sept 2009, No MIT on file, As noted in previous inspection, Form 4 on file Document number 1953795 for Temporarily Abandoned status dated 11/01/2013, Two year date to MIT the well has passed.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: Murray, Richard

Corrective Action: _____		Date: _____		
Reportable: _____	GPS: Lat _____	Long _____		
Proximity to Surface Water: _____		Depth to Ground Water: _____		
<b>Water Well:</b>				
DWR Receipt Num: _____		Owner Name: _____	GPS : _____	
<b>Field Parameters:</b>				
Sample Location: _____				
<b>Complaint:</b>				
Tracking Num	Category	Assigned To	Description	Incident Date
200221234	ORPHANED EQUIPMENT	Baroumand, Soraya	BLM has requested that the decommissioned storage tank be removed, in addition to miscellaneous equipment no longer in use be removed.	10/29/2009
200221234	RECLAMATION	Baroumand, Soraya	BLM has requested that the small enclosed pit be drained, filled, and seeded; followed by fence removal.	10/29/2009
200221234	TANK BATTERY	Baroumand, Soraya	BLM has requested that the replacement tank needs secondary containment.	10/29/2009
200221234	WEEDS	Baroumand, Soraya	BLM has requested the removal or/and control of noxious weeds (bull & canadian thistle and hounds tongue).	10/29/2009
Emission Control Burner (ECB): N _____				
Comment: _____				
Pilot: _____ Wildlife Protection Devices (fired vessels): YES _____				
<b>Reclamation - Storm Water - Pit</b>				
<b>Interim Reclamation:</b>				
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____		
Land Use: _____				
Comment: _____				
1003a. Waste and Debris removed? Pass _____				
CM _____		CA Date _____		
Unused or unneeded equipment onsite? Pass _____				
CM _____		CA Date _____		
Pit, cellars, rat holes and other bores closed? Pass _____				
CM _____		CA Date _____		
Guy line anchors marked? _____				
CM _____		CA Date _____		
1003b. Area no longer in use? _____ Production areas stabilized ? _____				
1003c. Compacted areas have been cross ripped? _____				

Inspector Name: Murray, Richard

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_  
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_  
**RESTORATION AND REVEGETATION**  
Cropland  
Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_  
Non-Cropland  
Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_  
1003 f. Weeds Noxious weeds? \_\_\_\_\_  
Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_  
Final Land Use: \_\_\_\_\_  
Reminder: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_  
Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

<b><u>Storm Water:</u></b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Compaction	Pass					
		Gravel	Pass			
		Culverts	Pass			
		Ditches	Pass			

S/A/V: SATISFACTOR \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
Y  
Comment: \_\_\_\_\_  
CA: \_\_\_\_\_

Inspector Name: Murray, Richard

Pits: ☒ NO SURFACE INDICATION OF PIT

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802200	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3873014">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3873014</a>
666802224	maralex 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872989">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872989</a>
666802225	maralex 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872990">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872990</a>
666802226	maralex 3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872991">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3872991</a>