

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/07/2016
Document Number:
666802232
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>295456</u>	<u>336037</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10079</u>
Name of Operator:	<u>ANTERO RESOURCES PICEANCE LLC</u>
Address:	<u>1625 17TH ST STE 300</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
ALBERTS, JERRY		jalberts@anteroresources.com	ANTERO EHS MANAGER

Compliance Summary:

QtrQtr:	<u>NWNE</u>	Sec:	<u>14</u>	Twp:	<u>6S</u>	Range:	<u>93W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/02/2016	680100416	AL	RI	SATISFACTORY		Pass	No
06/11/2013	670200553	XX	UN	SATISFACTORY			No
12/10/2010	200287168	PR	ND	SATISFACTORY			No
08/15/2007	200193844	DG	DG	SATISFACTORY			No

Inspector Comment:

Inspection is for wells with the status of Abandoned Location

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
295456	WELL	AL	06/24/2013	LO	045-15762	Gypsum Ranch B1	AL	<input checked="" type="checkbox"/>
295457	WELL	AL	06/24/2013	LO	045-15763	Gypsum Ranch B2	AL	<input checked="" type="checkbox"/>
296416	WELL	PR	06/10/2008	GW	045-16013	GYP SUM RANCH B3	PR	<input type="checkbox"/>
296417	WELL	AL	06/24/2013	LO	045-16014	Gypsum Ranch B12	AL	<input checked="" type="checkbox"/>
296454	WELL	PR	06/13/2008	GW	045-16036	GYP SUM RANCH B4	PR	<input type="checkbox"/>
296455	WELL	AL	06/24/2013	LO	045-16037	Gypsum Ranch B5	AL	<input checked="" type="checkbox"/>
296456	WELL	AL	06/24/2013	LO	045-16038	Gypsum Ranch B6	AL	<input checked="" type="checkbox"/>
296457	WELL	DG	04/16/2008	GW	045-16039	GYP SUM RANCH B7	DG	<input type="checkbox"/>

296458	WELL	AL	06/24/2013	LO	045-16040	Gypsum Ranch B8	AL	<input checked="" type="checkbox"/>
296459	WELL	PR	06/13/2008	GW	045-16041	GYPSUM RANCH B9	PR	<input type="checkbox"/>
296460	WELL	AL	06/24/2013	LO	045-16042	Gypsum Ranch B11	AL	<input checked="" type="checkbox"/>
296461	WELL	PR	02/01/2012	GW	045-16043	GYPSUM RANCH B13	PR	<input type="checkbox"/>
299255	WELL	AL	06/24/2013	LO	045-17626	Gypsum Ranch B10	AL	<input checked="" type="checkbox"/>
426957	NONFACILIT Y	AC	12/19/2011		-	GYPSUM RANCH B PAD	AC	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:
-------	---	-------------------------------

Comment			
Corrective Action		Date:	

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 295456

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:**

CA: **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:**

CA: **Date:** _____

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: <u>295456</u>	Type: <u>WELL</u>	API Number: <u>045-15762</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: 295457	Type: WELL	API Number: 045-15763	Status: AL	Insp. Status: AL
Facility ID: 296417	Type: WELL	API Number: 045-16014	Status: AL	Insp. Status: AL
Facility ID: 296455	Type: WELL	API Number: 045-16037	Status: AL	Insp. Status: AL
Facility ID: 296456	Type: WELL	API Number: 045-16038	Status: AL	Insp. Status: AL
Facility ID: 296458	Type: WELL	API Number: 045-16040	Status: AL	Insp. Status: AL
Facility ID: 296460	Type: WELL	API Number: 045-16042	Status: AL	Insp. Status: AL
Facility ID: 299255	Type: WELL	API Number: 045-17626	Status: AL	Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:
 1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass
 CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: **No visual sign of wells, URSA has producing wells on location**

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT