

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2016

Document Number:

666802232

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 295456 | 336037 | Murray, Richard | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 10079Name of Operator: ANTERO RESOURCES PICEANCE LLCAddress: 1625 17TH ST STE 300City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|------------------------------|--------------------|
| ALBERTS, JERRY | | jalberts@anteroresources.com | ANTERO EHS MANAGER |

Compliance Summary:QtrQtr: NWNE Sec: 14 Twp: 6S Range: 93W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 01/02/2016 | 680100416 | AL | RI | SATISFACTORY | | Pass | No |
| 06/11/2013 | 670200553 | XX | UN | SATISFACTORY | | | No |
| 12/10/2010 | 200287168 | PR | ND | SATISFACTORY | | | No |
| 08/15/2007 | 200193844 | DG | DG | SATISFACTORY | | | No |

Inspector Comment:

Inspection is for wells with the status of Abandoned Location

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|-------------------------------------|
| 295456 | WELL | AL | 06/24/2013 | LO | 045-15762 | Gypsum Ranch B1 | AL | <input checked="" type="checkbox"/> |
| 295457 | WELL | AL | 06/24/2013 | LO | 045-15763 | Gypsum Ranch B2 | AL | <input checked="" type="checkbox"/> |
| 296416 | WELL | PR | 06/10/2008 | GW | 045-16013 | GYPSUM RANCH B3 | PR | <input type="checkbox"/> |
| 296417 | WELL | AL | 06/24/2013 | LO | 045-16014 | Gypsum Ranch B12 | AL | <input checked="" type="checkbox"/> |
| 296454 | WELL | PR | 06/13/2008 | GW | 045-16036 | GYPSUM RANCH B4 | PR | <input type="checkbox"/> |
| 296455 | WELL | AL | 06/24/2013 | LO | 045-16037 | Gypsum Ranch B5 | AL | <input checked="" type="checkbox"/> |
| 296456 | WELL | AL | 06/24/2013 | LO | 045-16038 | Gypsum Ranch B6 | AL | <input checked="" type="checkbox"/> |
| 296457 | WELL | DG | 04/16/2008 | GW | 045-16039 | GYPSUM RANCH B7 | DG | <input type="checkbox"/> |

Inspector Name: Murray, Richard

| | | | | | | | | |
|--------|-----------------|----|------------|----|-----------|-----------------------|----|-------------------------------------|
| 296458 | WELL | AL | 06/24/2013 | LO | 045-16040 | Gypsum Ranch B8 | AL | <input checked="" type="checkbox"/> |
| 296459 | WELL | PR | 06/13/2008 | GW | 045-16041 | GYPSUM RANCH B9 | PR | <input type="checkbox"/> |
| 296460 | WELL | AL | 06/24/2013 | LO | 045-16042 | Gypsum Ranch B11 | AL | <input checked="" type="checkbox"/> |
| 296461 | WELL | PR | 02/01/2012 | GW | 045-16043 | GYPSUM RANCH B13 | PR | <input type="checkbox"/> |
| 299255 | WELL | AL | 06/24/2013 | LO | 045-17626 | Gypsum Ranch B10 | AL | <input checked="" type="checkbox"/> |
| 426957 | NONFACILIT Y | AC | 12/19/2011 | | - | GYPSUM RANCH B PAD | AC | <input type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

LocationLease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|---------------------------------|---------|-------------------|------|
| | | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|---------------------------------|---------|-------------------|---------|
| | | | | |

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|---------------------------------|---------|-------------------|---------|
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
| | | | | |

☐ Multiple Spills and Releases?Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|---------------------------------|---------|-------------------|---------|
| | | | | |

Equipment:

| Type: | # | Satisfactory/Action Required: |
|-------|---|-------------------------------|
| | | |

Inspector Name: Murray, Richard

| | |
|-------------------|-------|
| Comment | |
| Corrective Action | Date: |

Venting:

| | |
|---------|--|
| Yes/No | |
| Comment | |

Flaring:

| | | | |
|--------------------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
| Comment: | | | |
| Corrective Action: | | Correct Action Date: | |

Predrill

Location ID: 295456

Lease Road Adeq.: Pads: Soil Stockpile:

S/AR: Corrective Action: Date: CDP Num.:

Form 2A COAs:

S/AR: Comment: Date:

CA: Date:

Wildlife BMPs:

S/AR: Comment: Date:

CA: Date:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address: Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number: Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 295456 | Type: | WELL | API Number: | 045-15762 | Status: | AL | Insp. Status: | AL |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|

Inspector Name: Murray, Richard

| | | | | | | | | | |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 295457 | Type: | WELL | API Number: | 045-15763 | Status: | AL | Insp. Status: | AL |
| Facility ID: | 296417 | Type: | WELL | API Number: | 045-16014 | Status: | AL | Insp. Status: | AL |
| Facility ID: | 296455 | Type: | WELL | API Number: | 045-16037 | Status: | AL | Insp. Status: | AL |
| Facility ID: | 296456 | Type: | WELL | API Number: | 045-16038 | Status: | AL | Insp. Status: | AL |
| Facility ID: | 296458 | Type: | WELL | API Number: | 045-16040 | Status: | AL | Insp. Status: | AL |
| Facility ID: | 296460 | Type: | WELL | API Number: | 045-16042 | Status: | AL | Insp. Status: | AL |
| Facility ID: | 299255 | Type: | WELL | API Number: | 045-17626 | Status: | AL | Insp. Status: | AL |

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: **No visual sign of wells, URSA has producing wells on location**

Corrective Action: _____ Date _____

Overall Final Reclamation PassWell Release on Active Location ☒Multi-Well Location ☒

Inspector Name: Murray, Richard

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 666802232 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3873505 |