

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2016

Document Number:

674103219

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>418878</u>	<u>418880</u>	<u>Rickard, Jeff</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100322</u>
Name of Operator:	<u>NOBLE ENERGY INC</u>
Address:	<u>1625 BROADWAY STE 2200</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Compliance Summary:

QtrQtr:	<u>NENW</u>	Sec:	<u>5</u>	Twp:	<u>5N</u>	Range:	<u>66W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/04/2011	200299673	PR	PR	SATISFACTORY	I		No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
418878	WELL	PR	03/21/2011	OW	123-32052	WIEDEMAN 6-5	PR	<input checked="" type="checkbox"/>
418881	WELL	PR	03/16/2011	OW	123-32054	WIEDEMAN 25-5	PR	<input checked="" type="checkbox"/>
418883	WELL	PR	03/21/2011	OW	123-32055	WIEDEMAN 18-5	PR	<input checked="" type="checkbox"/>
418884	WELL	PR	03/16/2011	OW	123-32056	WIEDEMAN 29-5	PR	<input checked="" type="checkbox"/>
418885	WELL	PR	03/18/2011	OW	123-32057	WIEDEMAN 22-5	PR	<input checked="" type="checkbox"/>
418886	WELL	PR	03/26/2011	OW	123-32058	WIEDEMAN 4-5	PR	<input checked="" type="checkbox"/>
418887	WELL	PR	03/16/2011	OW	123-32059	WIEDEMAN 5-5	PR	<input checked="" type="checkbox"/>
418901	WELL	PR	10/01/2014	OW	123-32062	WIEDEMAN 3-5	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Inspector Name: Rickard, Jeff

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>8</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>8</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:	Date:

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Correct Action Date:

Predrill

Location ID: 418878

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	walkerv	Kerr-McGee Oil & Gas Onshore LP will implement site-specific best management practices in accordance with good engineering practices, including, but not limited to, construction of a berm or diversion dike, site grading, or other comparable measures, sufficient to protect an irrigation ditch 315 feet West and an Intermittent Stream 183' Northwest of the Wiedeman 25-5 oil and gas location from a release of drilling, completion, produced fluids, and chemical products	08/20/2010

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 418878 Type: WELL API Number: 123-32052 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418881 Type: WELL API Number: 123-32054 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418883 Type: WELL API Number: 123-32055 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418884 Type: WELL API Number: 123-32056 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418885 Type: WELL API Number: 123-32057 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418886 Type: WELL API Number: 123-32058 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418887 Type: WELL API Number: 123-32059 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Facility ID: 418901 Type: WELL API Number: 123-32062 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Braden head is exposed at surface.

CA:

CA Date:

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB): Y

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: IRRIGATED

Comment:

1003a. Waste and Debris removed?

CM

CA CA Date

Unused or unneeded equipment onsite?

CM _____
CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____
CA _____ CA Date _____

Guy line anchors marked? _____

CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Inspector Name: Rickard, Jeff

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT