

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2016

Document Number:

674003908

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 273437 | 332479 | Carlile, Craig | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|----------------|-------------------------------|-----------------|
| , Inspections | | COGCCinspections@Anadarko.com | All Inspections |
| , Reddy | | luke.reddy@anadarko.com | |
| Avant, Paul | (720) 929-6457 | Paul.Avant@Anadarko.com | All Inspections |

Compliance Summary:QtrQtr: NESW Sec: 11 Twp: 3N Range: 66W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 06/07/2013 | 667601408 | PR | PR | SATISFACTORY | P | | No |
| 03/08/2005 | 200067921 | PR | PR | SATISFACTORY | | Pass | No |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 273437 | WELL | PR | 09/21/2011 | GW | 123-22353 | PENTON 23-11 | PR |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Inspector Name: Carlile, Craig

| | | | | |
|--------------------|------------------------------|---------|-------------------|------|
| Lease Road: | | | | |
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| | | | | |

| | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Signs/Marker: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Good Housekeeping: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| | | | | |
|----------------|------|--------|-------------------|---------|
| Spills: | | | | |
| Type | Area | Volume | Corrective action | CA Date |
| | | | | |

☐ Multiple Spills and Releases?

| | | | | |
|------------------|------------------------------|---------|-------------------|---------|
| Fencing/: | | | | |
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | Pipe | | |

| | | | | |
|--------------------|-----|--|--|--|
| Equipment: | | | | |
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: SATISFACTORY | | |
| Comment | | | | |
| Corrective Action | | | | Date: |

| | | | | |
|---|---|----------|------------------------------|------------------------|
| Facilities: <input type="checkbox"/> New Tank Tank ID: _____ | | | | |
| Contents | # | Capacity | Type | SE GPS |
| | | | CENTRALIZED BATTERY | , |
| S/AR | | Comment: | Shared with API 05-123-15875 | |
| Corrective Action: | | | | Corrective Date: _____ |

Paint

| | |
|-----------|--|
| Condition | |
|-----------|--|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| | | | | |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
| Comment | | | |

Venting:

Yes/No

Comment

Flaring:

Type

Satisfactory/Action Required

Comment:

Corrective Action:

Correct Action

Date:

Predrill

Location ID: 273437

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 0 Type: _____ API Number: - Status: _____ Insp. Status: _____

Environmental

Inspector Name: Carlile, Craig

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Inspector Name: Carlile, Craig

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR
Y Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---------------------|----------|------------|
| Routine inspection. | carlilec | 06/09/2016 |