

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/06/2016
Document Number:
674702791
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>335568</u>	<u>335568</u>	<u>LONGWORTH, MIKE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10516</u>
Name of Operator:	<u>LINN OPERATING INC</u>
Address:	<u>600 TRAVIS STREET #5100</u>
City:	<u>HOUSTON</u> State: <u>TX</u> Zip: <u>77002</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Johnson, Derek	970-285-2200	dsjohnson@linenergy.com	
White, Brent		bwhite@linenergy.com	Production Foreman
Burns, Bryan		bburns@linenergy.com	
Freeman, Sarah		sarah.freeman@state.co.us	
Foster, Michael	281-840-4375	MFoster@linenergy.com	Regulatory Compliance Specialist II

Compliance Summary:

QtrQtr: NWSE Sec: 15 Twp: 5S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/25/2015	674701871			ACTION REQUIRED			No
08/20/2014	674700211			SATISFACTORY			No

Inspector Comment:

Permits have expired for Not Drilled wells. Two open conductors with open ratnoles and cellars.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
280075	WELL	XX	11/12/2013	LO	045-11174	LONG RIDGE 15B J15 595	ND	<input checked="" type="checkbox"/>
280584	WELL	XX	11/12/2013	LO	045-11295	LONG RIDGE 02D J15 595	ND	<input checked="" type="checkbox"/>
280587	WELL	XX	11/12/2013	LO	045-11292	LONG RIDGE 10C J15 595	ND	<input checked="" type="checkbox"/>
280588	WELL	XX	11/12/2013	LO	045-11291	LONG RIDGE 10B J15 595	ND	<input checked="" type="checkbox"/>
280596	WELL	PR	01/30/2011	GW	045-11290	LONG RIDGE 06D J15 595	PR	<input type="checkbox"/>
280597	WELL	XX	11/12/2013	LO	045-11289	LONG RIDGE 10D J15 595	ND	<input checked="" type="checkbox"/>
280598	WELL	PR	12/11/2014	GW	045-11288	LONG RIDGE LR15D J15 595	PR	<input type="checkbox"/>

280599	WELL	PR	12/15/2011	GW	045-11287	LONG RIDGE 06A J15 595	PR	<input type="checkbox"/>
289284	PIT	AC	02/16/2007		-	LONG RIDGE FRAC PIT LR15D J15 595	AC	<input type="checkbox"/>
443342	LAND APPLICATIO N SITE	AC	09/25/2015		-	Long Ridge J15 595	AC	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action		Date:	

Venting:

Yes/No	
--------	--

Comment	
---------	--

Flaring:

Type	Satisfactory/Action Required	
Comment:		
Corrective Action:	Correct Action	Date:

Predrill

Location ID: 335568

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: <u>280075</u>	Type: <u>WELL</u>	API Number: <u>045-11174</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>280584</u>	Type: <u>WELL</u>	API Number: <u>045-11295</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>280587</u>	Type: <u>WELL</u>	API Number: <u>045-11292</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

Facility ID: 280588 Type: WELL API Number: 045-11291 Status: XX Insp. Status: ND

Facility ID: 280597 Type: WELL API Number: 045-11289 Status: XX Insp. Status: ND

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____
 1003a. Waste and Debris removed? _____
 CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____
 CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____
 CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____
 1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Permits have expired for Not Drilled wells. Two open conductors with open ratholes and cellars.	longworm	06/09/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674702801	Two conductors set on location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3875772