

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/02/2016
Document Number:
668004460
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|--------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>260251</u> | <u>308033</u> | <u>DURAN, JOHN</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: PO BOX 6501
City: ENGLEWOOD State: CO Zip: 80155

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|-------------------------------|-----------------------------|
| Begano, Mary | 719-859-1918/719-846-2102 | mary_begano@xtoenergy.com | All Inspections |
| Harrison, Lyndon | 505-333-3100 | Lyndon_Harrison@xtoenergy.com | |
| Trujillo, Irwin | 719-846-0272/719-859-2264 | irwin_trujillo@xtoenergy.com | Sr. Env. Tech., Raton Basin |

Compliance Summary:

QtrQtr: SENE Sec: 13 Twp: 34S Range: 68W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 04/28/2015 | 668003360 | PR | PR | SATISFACTORY | P | | No |
| 03/21/2012 | 668000078 | PR | PR | SATISFACTORY | | | No |
| 04/29/2008 | 200189002 | PR | PR | ACTION REQUIRED | | | Yes |
| 03/16/2005 | 200068554 | PR | PR | SATISFACTORY | | Pass | No |
| 07/08/2002 | 200028737 | PR | WO | SATISFACTORY | | Pass | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|--|
| 260251 | WELL | PR | 03/25/2010 | GW | 071-07416 | APACHE CANYON 13-08V | PR <input checked="" type="checkbox"/> |
| 268857 | PIT | | 07/28/2003 | | - | APACHE CANYON 13-08V | <input type="checkbox"/> |

Equipment:

Location Inventory

Inspector Name: DURAN, JOHN

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
|------|------------------------------|---------|-------------------|------|
| | | | | |

Signs/Marker:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|----------------------|------------------------------|---------|-------------------|---------|
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____
 Comment: _____
 Corrective Action: _____

Good Housekeeping:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
| | | | | |

Multiple Spills and Releases?

Fencing/:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|-----------|------------------------------|---------|-------------------|---------|
| PUMP JACK | SATISFACTORY | | | |

Equipment:

| Type: | # | Satisfactory/Action Required: |
|-------------------|---|-------------------------------|
| | | |
| Comment | | |
| Corrective Action | | |
| | | Date: _____ |

Facilities:

New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|--------------|----------|---------------|------------------------|
| PRODUCED WATER | 1 | <50 BBLS | STEEL AST | , |
| S/AR | SATISFACTORY | Comment: | 1 - 30 bbl ST | |
| Corrective Action: | | | | Corrective Date: _____ |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Inspector Name: DURAN, JOHN

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | | | |
|-------------------|--|-----------------|--|
| Corrective Action | | Corrective Date | |
|-------------------|--|-----------------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Venting:

| | |
|--------|--|
| Yes/No | |
|--------|--|

| | |
|---------|--|
| Comment | |
|---------|--|

Flaring:

| | | | |
|------|--|------------------------------|--|
| Type | | Satisfactory/Action Required | |
|------|--|------------------------------|--|

Comment: _____

| | | | |
|--------------------|--|----------------------|--|
| Corrective Action: | | Correct Action Date: | |
|--------------------|--|----------------------|--|

Predrill

Location ID: 260251

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 260251 Type: WELL API Number: 071-07416 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

| | | | |
|---|-------------------|-------------|------|
| Water Well: | | Lat | Long |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |
| Field Parameters: | | | |
| | | | |
| Sample Location: _____ | | | |
| | | | |
| Emission Control Burner (ECB): _____ | | | |
| Comment: _____ | | | |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ | | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR Corrective Date: _____
Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/A/V): SATISFACTOR Comment: 30' x 60'

Corrective Action: _____ Date: _____

Inspector Name: DURAN, JOHN

| | | |
|-------------|-----------------|---------|
| Monitoring: | Monitoring Type | Comment |
| | Other | Stake |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 668004460 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3876229 |