



photo 1: Facing northwest toward the cement pad (1) at Lat/Long: 40.08697,-103.68970.Truck arrived to haul out the remaining debris.



photo 2: The remaining debris was broken apart for removal.



photo 3: The remaining debris was loaded into the trailer and hauled off to the local landfill.



photo 4: Once all the debris was removed the location was releveled and contoured.



photo 5: Facing east where cement pad (1) was removed.



photo 6: Facing north where cement pad (1) was removed.