

Voloshin 3-25

Inspection# 673403250

Stained soil on location, absorbent rags have become debris. Hard hat for scale.



Stained soil on location. Hard hat for scale.

Stained soil outside of tank berm. Hard hat for scale.



Stained soil outside of tank berm. Hard hat for scale.



Voloshin #3-25 cellar filled with fluid with sheen on top. Stained soil around cellar perimeter.



Close up of fluid and sheen in Voloshin #3-25 cellar. Plywood debris also visible.



Sheen on fluid in
Voloshin #3-25 cellar.
Plywood debris in cellar.



Fluid with sheen in
Kowach #3-25 cellar.



Close up of fluid with sheen and product visible in Kowach #3-25 cellar. Stained soil around perimeter of cellar.



Stained soil around wellhead area of Kowach #3-25. Hard hat for scale.

