



**photo 1:** Center of the location facing north. T-post remains at center of location.



**photo 2:** Center of the location facing west. Photo shows undesirable weed growth (kochia) throughout this area.



**photo 3:** View of undesirable weed growth (kochia).



**photo 4:** Facing west near center of the location. Vegetation has not adequately established in this area.



photo 5: South side of the location facing north. Vegetation has not adequately established in this area.



photo 6: South side facing east. T-post and wire remain around the perimeter of the location.



**photo 7:** Facing toward the east side of the location. T-post and wire remain around the perimeter of the location.



**photo 8:** Facing west toward the surrounding undisturbed pasture.