

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/14/2016

Document Number:

666802270

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	278649	336017	Murray, Richard	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 10079Name of Operator: ANTERO RESOURCES PICEANCE LLCAddress: 1625 17TH ST STE 300City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
ALBERTS, JERRY		jalberts@anteroresources.com	ANTERO EHS MANAGER

**Compliance Summary:**QtrQtr: SWNW Sec: 12 Twp: 6S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/30/2008	200205860	PR	ND	SATISFACTORY			No

**Inspector Comment:**Inspection is for wells with the status of Abandoned Location**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
278649	WELL	AL	06/21/2013	LO	045-10905	North Bank E17	AL	<input checked="" type="checkbox"/>
282544	WELL	PR	09/21/2012	GW	045-11777	NORTH BANK E1	PR	<input type="checkbox"/>
292121	WELL	PR	01/24/2008	GW	045-14603	NORTH BANK E5	PR	<input type="checkbox"/>
292127	WELL	PR	01/25/2008	GW	045-14602	NORTH BANK E3	PR	<input type="checkbox"/>
292129	WELL	AL	06/21/2013	LO	045-14601	North Bank E7	AL	<input checked="" type="checkbox"/>
295545	PIT	CL	03/28/2013		-	NORTH BANK E PAD	CL	<input type="checkbox"/>
295744	WELL	AL	06/21/2013	LO	045-15810	North Bank E11	AL	<input checked="" type="checkbox"/>
295745	WELL	PR	04/06/2010	GW	045-15809	NORTH BANK E12	PR	<input checked="" type="checkbox"/>
295746	WELL	AL	06/24/2013	LO	045-15808	North Bank E8	AL	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

295747	WELL	AL	06/24/2013	LO	045-15807	North Bank E9	AL	<input checked="" type="checkbox"/>
295748	WELL	AL	06/24/2013	LO	045-15806	North Bank E2	AL	<input checked="" type="checkbox"/>
295749	WELL	AL	06/24/2013	LO	045-15805	North Bank E6	AL	<input checked="" type="checkbox"/>
296470	WELL	AL	06/24/2013	LO	045-16046	North Bank E18	AL	<input checked="" type="checkbox"/>
296471	WELL	AL	06/24/2013	LO	045-16047	North Bank E19	AL	<input checked="" type="checkbox"/>
296472	WELL	AL	06/24/2013	LO	045-16048	North Bank E15	AL	<input checked="" type="checkbox"/>
412790	WELL	AL	06/21/2013	LO	045-18611	NORTH BANK E10	AL	<input checked="" type="checkbox"/>
412791	WELL	AL	06/21/2013	LO	045-18612	NORTH BANK E13	AL	<input checked="" type="checkbox"/>
412792	WELL	AL	06/21/2013	LO	045-18613	NORTH BANK E14	AL	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Equipment:</b>				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

<b>Venting:</b>	
Yes/No	
Comment	

<b>Flaring:</b>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

**Predrill**

Location ID: 278649

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 278649 Type: WELL API Number: 045-10905 Status: AL Insp. Status: AL

Facility ID: 292129 Type: WELL API Number: 045-14601 Status: AL Insp. Status: AL

Facility ID: 295744 Type: WELL API Number: 045-15810 Status: AL Insp. Status: AL

Facility ID: 295745 Type: WELL API Number: 045-15809 Status: PR Insp. Status: PR

Facility ID: 295746 Type: WELL API Number: 045-15808 Status: AL Insp. Status: AL

Facility ID: 295747 Type: WELL API Number: 045-15807 Status: AL Insp. Status: AL

Facility ID: 295748 Type: WELL API Number: 045-15806 Status: AL Insp. Status: AL

Inspector Name: Murray, Richard

Facility ID: 295749	Type: WELL	API Number: 045-15805	Status: AL	Insp. Status: AL
Facility ID: 296470	Type: WELL	API Number: 045-16046	Status: AL	Insp. Status: AL
Facility ID: 296471	Type: WELL	API Number: 045-16047	Status: AL	Insp. Status: AL
Facility ID: 296472	Type: WELL	API Number: 045-16048	Status: AL	Insp. Status: AL
Facility ID: 412790	Type: WELL	API Number: 045-18611	Status: AL	Insp. Status: AL
Facility ID: 412791	Type: WELL	API Number: 045-18612	Status: AL	Insp. Status: AL
Facility ID: 412792	Type: WELL	API Number: 045-18613	Status: AL	Insp. Status: AL

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment:

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

#### Water Well:

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

#### Field Parameters:

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

### Reclamation - Storm Water - Pit

#### Interim Reclamation:

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment:

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled PassDebris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: URSA has producing wells on location, No visual sign of wells

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation Pass Well Release on Active Location ☒ Multi-Well Location ☒

Inspector Name: Murray, Richard

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT