

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/14/2016
Document Number:
666802270
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>278649</u>	<u>336017</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>10079</u>
Name of Operator:	<u>ANTERO RESOURCES PICEANCE LLC</u>
Address:	<u>1625 17TH ST STE 300</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
ALBERTS, JERRY		jalberts@anteroresources.com	ANTERO EHS MANAGER

Compliance Summary:

QtrQtr: SWNW Sec: 12 Twp: 6S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/30/2008	200205860	PR	ND	SATISFACTORY			No

Inspector Comment:

Inspection is for wells with the status of Abandoned Location

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
278649	WELL	AL	06/21/2013	LO	045-10905	North Bank E17	AL	<input checked="" type="checkbox"/>
282544	WELL	PR	09/21/2012	GW	045-11777	NORTH BANK E1	PR	<input type="checkbox"/>
292121	WELL	PR	01/24/2008	GW	045-14603	NORTH BANK E5	PR	<input type="checkbox"/>
292127	WELL	PR	01/25/2008	GW	045-14602	NORTH BANK E3	PR	<input type="checkbox"/>
292129	WELL	AL	06/21/2013	LO	045-14601	North Bank E7	AL	<input checked="" type="checkbox"/>
295545	PIT	CL	03/28/2013		-	NORTH BANK E PAD	CL	<input type="checkbox"/>
295744	WELL	AL	06/21/2013	LO	045-15810	North Bank E11	AL	<input checked="" type="checkbox"/>
295745	WELL	PR	04/06/2010	GW	045-15809	NORTH BANK E12	PR	<input checked="" type="checkbox"/>
295746	WELL	AL	06/24/2013	LO	045-15808	North Bank E8	AL	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

295747	WELL	AL	06/24/2013	LO	045-15807	North Bank E9	AL	<input checked="" type="checkbox"/>
295748	WELL	AL	06/24/2013	LO	045-15806	North Bank E2	AL	<input checked="" type="checkbox"/>
295749	WELL	AL	06/24/2013	LO	045-15805	North Bank E6	AL	<input checked="" type="checkbox"/>
296470	WELL	AL	06/24/2013	LO	045-16046	North Bank E18	AL	<input checked="" type="checkbox"/>
296471	WELL	AL	06/24/2013	LO	045-16047	North Bank E19	AL	<input checked="" type="checkbox"/>
296472	WELL	AL	06/24/2013	LO	045-16048	North Bank E15	AL	<input checked="" type="checkbox"/>
412790	WELL	AL	06/21/2013	LO	045-18611	NORTH BANK E10	AL	<input checked="" type="checkbox"/>
412791	WELL	AL	06/21/2013	LO	045-18612	NORTH BANK E13	AL	<input checked="" type="checkbox"/>
412792	WELL	AL	06/21/2013	LO	045-18613	NORTH BANK E14	AL	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:			Correct Action Date:

Predrill

Location ID: 278649
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____
CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____
CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 278649 Type: WELL API Number: 045-10905 Status: AL Insp. Status: AL

Facility ID: 292129 Type: WELL API Number: 045-14601 Status: AL Insp. Status: AL

Facility ID: 295744 Type: WELL API Number: 045-15810 Status: AL Insp. Status: AL

Facility ID: 295745 Type: WELL API Number: 045-15809 Status: PR Insp. Status: PR

Facility ID: 295746 Type: WELL API Number: 045-15808 Status: AL Insp. Status: AL

Facility ID: 295747 Type: WELL API Number: 045-15807 Status: AL Insp. Status: AL

Facility ID: 295748 Type: WELL API Number: 045-15806 Status: AL Insp. Status: AL

Facility ID: <u>295749</u>	Type: <u>WELL</u>	API Number: <u>045-15805</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>296470</u>	Type: <u>WELL</u>	API Number: <u>045-16046</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>296471</u>	Type: <u>WELL</u>	API Number: <u>045-16047</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>296472</u>	Type: <u>WELL</u>	API Number: <u>045-16048</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412790</u>	Type: <u>WELL</u>	API Number: <u>045-18611</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412791</u>	Type: <u>WELL</u>	API Number: <u>045-18612</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>412792</u>	Type: <u>WELL</u>	API Number: <u>045-18613</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:
 1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass
 CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: **URSA has producing wells on location, No visual sign of wells**

Corrective Action: _____ Date _____

Overall Final Reclamation Pass Well Release on Active Location Multi-Well Location

Inspector Name: Murray, Richard

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802270	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3878815