

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/14/2016

Document Number:

674702815

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335937	335937	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	100185
Name of Operator:	ENCANA OIL & GAS (USA) INC
Address:	370 17TH ST STE 1700
City:	DENVER
State:	CO
Zip:	80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:

QtrQtr:	SWSW	Sec:	33	Twp:	4S	Range:	96W
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/15/2015	674701269			ACTION REQUIRED			No
10/21/2014	674700431			SATISFACTORY			No
10/21/2014	674700430			SATISFACTORY			No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292358	WELL	PR	07/05/2008	GW	045-14698	DWU CP14D-33 M33 49	PR
292359	WELL	PR	07/05/2008	GW	045-14700	DWU CP08D-32 M33 49	PR
292360	WELL	WO	02/13/2008	SI	045-14699	DWU CP11D-33 M33 49	WO
292361	WELL	PR	07/05/2008	GW	045-14701	DWU CP13B-33 M33 49	PR
413161	WELL	AL	11/16/2011	LO	045-18717	DOUBLE WILLOW UNIT CP09SW-33 M33 4	AL <input checked="" type="checkbox"/>
413162	WELL	AL	11/16/2011	LO	045-18718	DOUBLE WILLOW UNIT CP05SW-33 M33 4	AL <input checked="" type="checkbox"/>
413163	WELL	AL	11/16/2011	LO	045-18720	DOUBLE WILLOW UNIT CP02SW-33 M33 4	AL <input checked="" type="checkbox"/>
413164	WELL	AL	11/16/2011	LO	045-18721	DOULBE WILLOW UNIT CP01SW-33 M33 4	AL <input checked="" type="checkbox"/>
413165	WELL	AL	11/16/2011	LO	045-18722	DOUBLE WILLOW UNIT CP08SW-33 M33 4	AL <input checked="" type="checkbox"/>

413166	WELL	AL	11/16/2011	LO	045-18723	DOUBLE WILLOW UNIT CP03SW-33 M33 4	AL	<input checked="" type="checkbox"/>
413167	WELL	AL	11/16/2011	LO	045-18719	DOUBLE WILLOW UNIT CP06SW-33 M33 4	AL	<input checked="" type="checkbox"/>
425573	PIT	CL	03/30/2015		-	M33 NORTH 496	CL	<input type="checkbox"/>
425585	PIT	CL	03/30/2015		-	M33 SOUTH 496	CL	<input type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:
Comment		
Corrective Action	Date: _____	

Venting:

Yes/No	
--------	--

Comment	
---------	--

Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date:

Predrill

Location ID: 335937

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: <u>413161</u>	Type: <u>WELL</u>	API Number: <u>045-18717</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>413162</u>	Type: <u>WELL</u>	API Number: <u>045-18718</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>
Facility ID: <u>413163</u>	Type: <u>WELL</u>	API Number: <u>045-18720</u>	Status: <u>AL</u>	Insp. Status: <u>AL</u>

Facility ID: 413164	Type: WELL	API Number: 045-18721	Status: AL	Insp. Status: AL
Facility ID: 413165	Type: WELL	API Number: 045-18722	Status: AL	Insp. Status: AL
Facility ID: 413166	Type: WELL	API Number: 045-18723	Status: AL	Insp. Status: AL
Facility ID: 413167	Type: WELL	API Number: 045-18719	Status: AL	Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment:
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment:
 1003a. Waste and Debris removed? _____
 CM _____ CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____
 CM _____ CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____
 CM _____ CA _____ CA Date _____
 Guy line anchors marked? _____
 CM _____

CA _____ CA Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: No evidence of "AL" wells on location.

Corrective Action: Date _____

Overall Final Reclamation _____ Pass _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674702815	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3879226
674702816	No evidence of "AL" wells	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3879219