

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2016

Document Number:

666802272

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	269185	335000	Murray, Richard	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:**Compliance Summary:**QtrQtr: NWSE Sec: 9 Twp: 7S Range: 92W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
269180	WELL	PR	06/11/2004	GW	045-09325	HILL 9-9 (J9E)	PR	<input checked="" type="checkbox"/>
269185	WELL	TA	06/29/2011	SI	045-09327	HILL 9-15A (J9E)	TA	<input checked="" type="checkbox"/>
269186	WELL	PR	04/26/2004	GW	045-09326	HILL 9-9B (J9E)	PR	<input checked="" type="checkbox"/>
269189	WELL	PA	12/19/2012	GW	045-09328	HILL 9-10B (J9E)	PA	<input type="checkbox"/>
269234	WELL	AL	12/06/2004	LO	045-09337	HILL 9-10 (J9E)	AL	<input type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Inspector Name: Murray, Richard

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Fencing:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type: Plunger Lift	# 2	Satisfactory/Action Required: SATISFACTORY		
Comment: _____				
Corrective Action: _____				Date: _____
Type: Gas Meter Run	# 1	Satisfactory/Action Required: SATISFACTORY		
Comment: _____				
Corrective Action: _____				Date: _____
Type: Vertical Heated Separator	# 3	Satisfactory/Action Required: SATISFACTORY		
Comment: _____				
Corrective Action: _____				Date: _____

Facilities: <input type="checkbox"/> New Tank Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
METHANOL	1	1000 GAL	STEEL AST	,
S/AR	SATISFACTORY Comment: Centralized battery			
Corrective Action: _____				Corrective Date: _____

Paint				
Condition	Adequate			
Other (Content) _____				
Other (Capacity) _____				
Other (Type) _____				

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Murray, Richard

Corrective Action					Corrective Date	
Comment						
Facilities: <input type="checkbox"/> New Tank Tank ID: _____						
Contents	#	Capacity	Type	SE GPS		
CONDENSATE	1	400 BBLS	STEEL AST	39.460037,-107.669090		
S/AR	SATISFACTORY		Comment:			
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content) _____						
Other (Capacity) _____						
Other (Type) _____						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Corrective Action					Corrective Date	
Comment						

<u>Venting:</u>	
Yes/No	NO
Comment	

<u>Flaring:</u>			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 269185

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 269180 Type: WELL API Number: 045-09325 Status: PR Insp. Status: PR

Producing WellComment: **Plunger lift**

Facility ID: 269185 Type: WELL API Number: 045-09327 Status: TA Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

S/A/V: SATISFACTORY CA Date: _____

CA: _____

Comment: _____

Inspector Name: Murray, Richard

Workover

Comment: MIT test, Bridge plug 3965', Start pressure 450psi Total 15 minute loss 2psi, O psi loss last 5 minutes, Bradenhead start pressure 0 psi after 15 minutes 52psi

Facility ID: 269186 Type: WELL API Number: 045-09326 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long
DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB): N

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed? Pass

CM

CA

CA Date

Unused or unneeded equipment onsite? Pass

CM

CA

CA Date

Pit, cellars, rat holes and other bores closed? Pass

CM

CA

CA Date

Guy line anchors marked?

CM

CA

CA Date

Inspector Name: Murray, Richard

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
Seeding	Pass					
		Culverts	Pass			
Compaction	Pass					

Inspector Name: Murray, Richard

S/A/V: SATISFACTOR
Y

Corrective Date: _____

Comment:

CA:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802272	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3880380