



**photo 1:** Facing northeast toward the location.



**photo 2:** South side of the location facing north.





**photo 3:** East side of the location facing west.



**photo 4:** Area at the center of the location has little to no vegetation establishment.





**photo 5:** North side of the location facing southwest. There was undesirable vegetation growing within this area.



**photo 6:** Undesirable vegetation (Russian thistle, kochia, pennycress) growing at the north side of the location.