

**Ross-Government-USA 43-7**

Inspection# 673403266

No capacity on tank labels.



No tank labels, no wildlife protection on exhaust.



Pit.



Land farm area with recent additions.

