



**photo 1:** 2014 aerial image of the location for reference.



**photo 2:** Center of the location facing north.



**photo 3:** Center of the location facing west.



**photo 4:** Center of the location facing south.



**photo 5:** Center of the location facing east.



**photo 6:** View of vegetation cover. The yellow area is undesirable vegetation growth (alyssum).



**photo 7:** View of groundcover. Undesirable vegetation (alyssum, kochia) shown in the photo.



**photo 8:** Facing north toward the surrounding undisturbed pasture.