



photo 1: 2014 aerial image of the location for reference.



photo 2: Center of the location facing north.



photo 3: Center of the location facing west.



photo 4: Center of the location facing south.



photo 5: Center of the location facing east.



photo 6: South side of the location facing north. The yellow areas are undesirable vegetation growth (alyssum).



photo 7: View of groundcover. Undesirable vegetation (alyssum, kochia) shown in the photo.



photo 8: Facing west toward the surrounding undisturbed pasture.