



photo 1: 2014 aerial image of the location for reference.



photo 2: Facing southwest toward the location.




photo 3: Southeast side of the location facing northwest.



photo 4: Southwest side of the location facing northeast.



photo 5: Northwest side of the location facing southeast.



photo 6: Facing west toward the surrounding undisturbed pasture.