

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/13/2016
Document Number:
668004505
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection <input type="checkbox"/>
	<u>276263</u>	<u>308607</u>	<u>DURAN, JOHN</u>	2A Doc Num: _____

Operator Information:

OGCC Operator Number: <u>10084</u>
Name of Operator: <u>PIONEER NATURAL RESOURCES USA INC</u>
Address: <u>5205 N O'CONNOR BLVD STE 200</u>
City: <u>IRVING</u> State: <u>TX</u> Zip: <u>75039</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Compliance Summary:

QtrQtr: SESE Sec: 23 Twp: 32S Range: 66W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/14/2014	668001833	PR	PR	SATISFACTORY	P		No
10/21/2010	200279982	ES	PR	ACTION REQUIRED			Yes
12/08/2009	200225192	PR	PR	SATISFACTORY			No
02/16/2006	200085558	PR	PR	SATISFACTORY		Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
276263	WELL	PR	04/28/2005	GW	071-08326	TRIMAX 44-23	PR	<input checked="" type="checkbox"/>
280415	PIT	AC	10/03/2005		-	TRIMAX 44-23 ONSITE	AC	<input type="checkbox"/>
420396	WELL	PR	11/05/2011	GW	071-09834	TRIMAX 44-23 TR	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>2</u>	Production Pits: <u>2</u>
Condensate Tanks: _____	Water Tanks: _____	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Mortors: <u>2</u>	Cavity Pumps: <u>2</u>	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>2</u>	Oil Pipeline: _____	Water Pipeline: <u>2</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: <u>2</u>	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:					
Type: Deadman # & Marked	# 8	Satisfactory/Action Required:	SATISFACTORY		
Comment					
Corrective Action				Date:	

Venting:	
Yes/No	
Comment	

Flaring:			
Type	Satisfactory/Action Required		
Comment:			
Corrective Action:			Correct Action Date:

Predrill

Location ID: 276263
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	koepsear	The pit should not be expanded beyond the current dimensions without submittal of a new form 15 and prior approval of the COGCC.	11/08/2010
OGLA	koepsear	48-hour spud notice will be provided to Peter Gintautas with the COGCC (719-679-1326) in order to inspect the pit prior to drilling the well.	11/08/2010

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 276263 Type: WELL API Number: 071-08326 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Facility ID: 420396 Type: WELL API Number: 071-09834 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: TIMBER
Comment: _____
1003a. Waste and Debris removed? _____
CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____
CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____
CM _____
CA _____ CA Date _____
Guy line anchors marked? _____
CM _____
CA _____ CA Date _____
1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: **TIMBER**

Reminder: _____

Comment:

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: **SATISFACTOR** Corrective Date: _____

Y

Comment:

CA:

Pits: NO SURFACE INDICATION OF PIT

Inspector Name: DURAN, JOHN

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/A/V): SATISFACTOR Comment: 30' x 70', shared

Corrective Action: _____ Date: _____

Monitoring:	Monitoring Type	Comment
	Chain	