

**BCU Pad 12B Follow Up**

**Inspection Doc# 675202953**

**These photo are representative and do not include all the debris found in berms and interim reclamation.**

Debris in berm



Debris in berm



Debris in reclaimed area

