

**USA-Clark – Millison 1**

Inspection# 673403273

Product in pit. No netting.



Previous operator on tank labels, insulation blowing off of tank, vegetation growing on and in berm.



No wildlife protection on exhaust in foreground.



Missing tank label.  
Vegetation growing on and in berm.



Equipment/unused equipment stored on location.



Equipment stored on location in foreground (tubing) and unused tanks in background.



Landfarm area GPS  
coordinates from point  
of this photo 40.91903, -  
108.30823

