



Photo#1: Overview of Location to SW.

June 9, 2016

Inspection Photos: Battlement Mesa - Noble Loc#334384



Photo#2: Looking up from base of Cut Slope to SE .

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#3: Seeping from base of Cut Slope pools and drains to NE.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#4: Close up of Seeping at base of slough area.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#5: Looking up Diversion Chanel from North end .

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#6: Rocked Chanel, view moving SE uphill

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#7: Rubber/plastic material lining Channel.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#10: Liner is failed at points & water undercuts ditch and drains to Cut Slope.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#9: : Liner is failed at points & water undercuts ditch and drains to Cut Slope.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#10: Sediment Build- Up is allowing water to overwhelm ditch banks and flow to Cut Slope.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#11: Sediment is Built up and allowing water to overwhelm ditch banks and flow to Cut Slope.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#12: View to NE over Cut Slope from SW side of Slope

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#13: Fissures at top of slough area, below lip of Subsidence.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#14: Subsidence area below Ditch #2

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#15: B List State & County Noxious Weeds, Hound's Tongue and Thistle found on Location.

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016



Photo#16: B List State & County Noxious Weeds, Hound's Tongue and Thistle found on Location

Inspection Photos: Battlement Mesa - Noble Loc#334384

June 9, 2016