

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/22/2016
Document Number:
673803372
Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|---------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>243312</u> | <u>319345</u> | <u>Gomez, Jason</u> | <input type="checkbox"/> | |

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Compliance Summary:

QtrQtr: NWNW Sec: 26 Twp: 5N Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 05/23/2012 | 661601477 | PR | PR | SATISFACTORY | | | No |
| 12/13/2010 | 200287436 | PR | PR | SATISFACTORY | | | No |
| 02/14/2005 | 200066449 | PR | PR | SATISFACTORY | | Pass | No |
| 02/28/2000 | 200004219 | PR | PR | SATISFACTORY | | Pass | No |
| 02/24/1998 | 500166566 | PR | PR | | | | |
| 02/27/1996 | 500166565 | PR | PR | | | Pass | Yes |
| 10/27/1994 | 500166564 | | PR | | | | No |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|--|
| 243312 | WELL | PR | 03/07/2003 | GW | 123-11103 | BLEHM 3 | PR <input checked="" type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|--------------------|------------------------------|---------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| | | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |
| WELLHEAD | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|---------------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|------------------------------|----------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | AG PANEL | | |

| Equipment: | | | | | |
|-------------------------------|-----|-------------------------------|--------------|-------|--|
| Type: Plunger Lift | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Gas Meter Run | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Pig Station | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Bird Protectors | # 2 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Emission Control Device | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |

| | | |
|-----------------------------------|-------|--|
| Type: Horizontal Heated Separator | # 1 | Satisfactory/Action Required: SATISFACTORY |
| Comment | | |
| Corrective Action | Date: | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|--------------|-----------|---------------------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLS | CONCRETE SUMP/VAULT | 40.377630,-104.868040 |
| S/AR | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|--------------------|--------------|----------|-----------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.377630,-104.868040 |
| S/AR | SATISFACTORY | | Comment: | |
| Corrective Action: | | | | Corrective Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------------------|----------|---------------------|---------------------|-----------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Venting:

| | |
|---------|----|
| Yes/No | NO |
| Comment | |

Flaring:

| | |
|----------|------------------------------|
| Type | Satisfactory/Action Required |
| Comment: | |

| | |
|--------------------|----------------------|
| Corrective Action: | Correct Action Date: |
|--------------------|----------------------|

Predrill

Location ID: 243312
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____
 CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 243312 Type: WELL API Number: 123-11103 Status: PR Insp. Status: PR

Producing Well

Comment: **PR**

BradenHead

Comment: **PLUMBED TO SURFACE**

CA: _____

CA Date: _____

Environmental

Spills/Releases:

Inspector Name: Gomez, Jason

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): Y
 Comment: _____
 Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: Gomez, Jason

Top soil replaced Pass Recontoured Pass Perennial forage re-established In

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT