

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
06/22/2016
Document Number:
681901050
Overall Inspection:
ACTION REQUIRED

FIELD INSPECTION FORM

| | | | | | |
|---------------------|---------------|---------------|------------------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | <u>240972</u> | <u>321500</u> | <u>HELGELAND, GARY</u> | <input type="checkbox"/> | |

Operator Information:

| | |
|-----------------------|---|
| OGCC Operator Number: | <u>10369</u> |
| Name of Operator: | <u>NATURAL RESOURCE GROUP INC</u> |
| Address: | <u>1789 W LITTLETON BLVD</u> |
| City: | <u>LITTLETON</u> State: <u>CO</u> Zip: <u>80120</u> |

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|---------------------------|---------------------------|-----------------|
| Bacon, Duane | 303-545-2620/303-579-6353 | energyoilandgas@gmail.com | All inspections |

Compliance Summary:

QtrQtr: NWNE Sec: 26 Twp: 1N Range: 68W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 07/22/2015 | 680700197 | PR | PR | ACTION REQUIRED | | | No |
| 06/26/2015 | 670901217 | PR | PR | ACTION REQUIRED | | | No |
| 03/23/2011 | 200304512 | PR | PR | ACTION REQUIRED | | | Yes |
| 02/20/2003 | 200035415 | PR | PR | SATISFACTORY | | Pass | No |
| 10/04/2001 | 200020497 | PR | PR | ACTION REQUIRED | | Fail | Yes |
| 09/18/2001 | 200020222 | ES | PR | ACTION REQUIRED | | Fail | Yes |
| 08/28/2001 | 200019794 | PR | PR | ACTION REQUIRED | | Fail | Yes |
| 11/16/1998 | 500163320 | PR | PR | | | Pass | No |
| 02/11/1998 | 500163319 | PR | PR | | | Fail | Yes |
| 07/28/1996 | 500163318 | PR | PR | | | | |
| 06/07/1996 | 500163317 | PR | PR | | | | |
| 04/23/1996 | 500163316 | PR | PR | | | | |
| 01/11/1996 | 500163315 | PR | PR | | | Fail | Yes |
| 01/10/1996 | 500163314 | CO | PR | | | | |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|-------------------------------------|
| 240972 | WELL | PR | 04/01/2013 | OW | 014-08760 | SHANNON-ROBERTS 3 | PR | <input checked="" type="checkbox"/> |

| Equipment: | | Location Inventory | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Lease Road: | | | | |
|-------------|------------------------------|---------|-------------------|------|
| Type | Satisfactory/Action Required | comment | Corrective Action | Date |
| | | | | |

| Signs/Marker: | | | | |
|----------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | | | |
| BATTERY | SATISFACTORY | | | |
| TANK LABELS/PLACARDS | SATISFACTORY | | | |

Emergency Contact Number (S/AR): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

| Good Housekeeping: | | | | |
|--------------------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| | | | | |

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|-----------|------------------------------|---------|-------------------|---------|
| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
| WELLHEAD | SATISFACTORY | Panel | | |

| Equipment: | | | | | |
|-----------------------------------|---|-------------------------------|-----------------|-----------------|--|
| Type: Gas Meter Run | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |
| Comment | | | | | |
| Corrective Action | | | | Date: | |
| Type: Bird Protectors | # 1 | Satisfactory/Action Required: | ACTION REQUIRED | | |
| Comment | Bird protector disconnected and laying on ground. | | | | |
| Corrective Action | Install bird protector | | | Date: 7/22/2016 | |
| Type: Horizontal Heated Separator | # 1 | Satisfactory/Action Required: | SATISFACTORY | | |

| | |
|-------------------|-------|
| Comment | |
| Corrective Action | Date: |

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|-----------|---|----------|-----------|------------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | 40.027718, -104.967388 |

| | | |
|------|--------------|----------|
| S/AR | SATISFACTORY | Comment: |
|------|--------------|----------|

| | |
|--------------------|------------------|
| Corrective Action: | Corrective Date: |
|--------------------|------------------|

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | |
|-------------------|-----------------|
| Corrective Action | Corrective Date |
|-------------------|-----------------|

| |
|---------|
| Comment |
|---------|

Facilities: New Tank Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|----------------|---|-----------|-----------|--------|
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | , |

| | | |
|------|--------------|----------|
| S/AR | SATISFACTORY | Comment: |
|------|--------------|----------|

| | |
|--------------------|------------------|
| Corrective Action: | Corrective Date: |
|--------------------|------------------|

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

| | |
|-------------------|-----------------|
| Corrective Action | Corrective Date |
|-------------------|-----------------|

| |
|---------|
| Comment |
|---------|

Venting:

| | |
|--------|----|
| Yes/No | NO |
|--------|----|

| |
|---------|
| Comment |
|---------|

Flaring:

| | |
|----------|------------------------------|
| Type | Satisfactory/Action Required |
| Comment: | |

| | |
|--------------------|----------------------|
| Corrective Action: | Correct Action Date: |
|--------------------|----------------------|

Predrill

Location ID: 240972

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 240972 Type: WELL API Number: 014-08760 Status: PR Insp. Status: PR

Producing Well

Comment: PR

BradenHead

Comment: Bradenhead is plumed to surface.

CA: _____

CA Date: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): N
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Waste and Debris removed? Pass
 CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass
 CM _____
 CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass
 CM _____
 CA _____ CA Date _____

Guy line anchors marked? _____
 CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland
 Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

S/A/V: SATISFACTOR Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT