

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2016

Document Number:

674702868

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335616	335616	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10516Name of Operator: LINN OPERATING INCAddress: 600 TRAVIS STREET #5100City: HOUSTON State: TX Zip: 77002

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Lujan, Carlos		carlos.lujan@state.co.us	
Burns, Bryan		bburns@linnenergy.com	
White, Brent		bwhite@linnenergy.com	Production Foreman
Foster, Michael	281-840-4375	MFoster@linnenergy.com	Regulatory Compliance Specialist II
Johnson, Derek	970-285-2200	dsjohnson@linnenergy.com	

Compliance Summary:QtrQtr: NWSE Sec: 13 Twp: 6S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/19/2015	674702068			SATISFACTORY			No
04/23/2014	671000032			ALLEGED VIOLATION			Yes
04/01/2014	663902910			SATISFACTORY			No
10/28/2013	663902322			SATISFACTORY	I		No
08/13/2013	663900691			SATISFACTORY	F		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
275991	WELL	PA	05/09/2011	GW	045-10414	CHEVRON 33B-13	PA	<input type="checkbox"/>
286649	WELL	PR	11/09/2009	GW	045-12719	CHEVRON 13-13D	PR	<input checked="" type="checkbox"/>
286650	WELL	PR	06/14/2008	GW	045-12718	CHEVRON 13-14D	PR	<input checked="" type="checkbox"/>
286651	WELL	PR	01/12/2010	GW	045-12717	CHEVRON 13-16D	PR	<input checked="" type="checkbox"/>
293707	WELL	PR	06/03/2008	GW	045-15112	CHEVRON 33B-13R	PR	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

293716	WELL	PR	05/03/2008	GW	045-15113	CHEVRON 275-13	PR	<input checked="" type="checkbox"/>
293717	WELL	PR	10/15/2009	GW	045-15114	CHEVRON 13-8D	PR	<input checked="" type="checkbox"/>
293718	WELL	PR	06/21/2008	GW	045-15115	CHEVRON 13-7D	PR	<input checked="" type="checkbox"/>
414674	PIT	CL	12/08/2009		-	J-13	CL	<input type="checkbox"/>
443305	LAND APPLICATION SITE	AC	09/24/2015		-	Chevron J13697	AC	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: _____

Comment: 970-285-2200

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Equipment:			
Type: Bird Protectors	# 9	Satisfactory/Action Required:	
Comment			
Corrective Action		Date:	
Type: Horizontal Heated Separator	#	Satisfactory/Action Required:	
Comment			
Corrective Action		Date:	
Type: Ancillary equipment	# 1	Satisfactory/Action Required:	SATISFACTORY
Comment		Chemical container at wells	
Corrective Action		Date:	
Type: Plunger Lift	# 7	Satisfactory/Action Required:	SATISFACTORY
Comment			
Corrective Action		Date:	

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____
Contents	#	Capacity	Type
CONDENSATE	1	100 BBLS	PBV STEEL
S/AR	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

Paint	
Condition	Adequate
Other (Content) _____	
Other (Capacity) _____	
Other (Type) _____	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action		Corrective Date		
Comment				

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____
Contents	#	Capacity	Type
METHANOL	1	<50 BBLS	STEEL AST
S/AR	SATISFACTORY	Comment:	
Corrective Action:		Corrective Date:	

Paint	
Condition	Adequate
Other (Content) _____	
Other (Capacity) 500 gallons	
Other (Type) _____	

Berms	
--------------	--

Inspector Name: LONGWORTH, MIKE

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action					Corrective Date
Comment					

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	300 BBLS	HEATED STEEL AST	,
S/AR	SATISFACTORY		Comment: Air id 045-1873-001	
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	NO
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 335616

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

S/AR: _____ Comment: _____

CA: _____ Date: _____

Comment: _____

Staking:**On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 286649 Type: WELL API Number: 045-12719 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 286650 Type: WELL API Number: 045-12718 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 286651 Type: WELL API Number: 045-12717 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 293707 Type: WELL API Number: 045-15112 Status: PR Insp. Status: PR

Producing WellComment: **Producing well**Facility ID: 293716 Type: WELL API Number: 045-15113 Status: PR Insp. Status: PR**Producing Well**Comment: **Producing well**Facility ID: 293717 Type: WELL API Number: 045-15114 Status: PR Insp. Status: PR**Producing Well**Comment: **Producing well**Facility ID: 293718 Type: WELL API Number: 045-15115 Status: PR Insp. Status: PR**Producing Well**Comment: **Producing well****Environmental****Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: **Land farm on north end of location.**

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? FailCM Unmarked anchors along east side of wellsCA Location is within a designated setback location, mark guy line anchors per Rule 604.c. (2)Q." CA Date 07/08/2016

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Inspector Name: LONGWORTH, MIKE

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
Compaction	Pass					
Berms	Pass					
				MHSP	Pass	
Seeding	Pass					
		Culverts	Pass			

S/A/V: SATISFACTOR
Y _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674702868	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3885482
674702872	Unmarked deadmen	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3885473