

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/21/2016

Document Number:

673713383

Overall Inspection:

SATISFACTORY w/ CMT  
or AR**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	204443	320679	Sherman, Susan	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	
Ingve, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections

**Compliance Summary:**QtrQtr: NWSW Sec: 36 Twp: 4S Range: 58W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/26/2016	673713228	TA	PA	SATISFACTORY			No
05/16/2016	673713190	TA	PA	SATISFACTORY			No
10/28/2014	673707450	TA	TA	SATISFACTORY	I		No
10/23/2013	600000056	TA	SI	SATISFACTORY	P		No
11/20/2007	200122126	MT	TA	SATISFACTORY			No
12/01/2005	200080513	ES	TA	SATISFACTORY		Pass	No
12/01/2000	896463	MT	TA	ACTION REQUIRED		Fail	Yes
11/30/1995	500134468	MT	TA			Pass	No
06/21/1995	500134471	ID	TA				Yes

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
204443	WELL	TA	12/01/2000	SI	005-06528	STATE 3	PA	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Inspector Name: Sherman, Susan

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

#### Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
DRILLING/RECOMP	SATISFACTORY			

Emergency Contact Number (S/AR): \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

#### Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

#### Equipment:

Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY
Comment	To be removed at time of cut, cap and cover or wellhead.	
Corrective Action		Date: _____

#### Venting:

Yes/No	
Comment	

#### Flaring:

Type	Satisfactory/Action Required
Comment:	
Corrective Action:	Correct Action Date: _____

**Predrill**

Location ID: 204443

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 204443 Type: WELL API Number: 005-06528 Status: TA Insp. Status: PA

**Cement****Cement Contractor**Contractor Name: Cementers WellContractor Phone: 970-353-7299**Surface Casing**

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

**Intermediate Casing**

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

**Production Casing**

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

**Plugging Operations**

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

**Comment:**

ATP water haulers. Water from Mitchell well outside of Bennett.  
 Set tubing at 1728' and pumped 75 sxs, 1% CaCl, 15.8# cement.  
 Set tubing at 210' and pumped 75 sxs, 1% CaC<sub>2</sub>, 15.8# cement to surface.  
 Check top of surface cement at time of cut, cap and cover of wellhead. Bring to surface if cement is low.  
 Remove stained soil at tank (see attached photo).

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Inspector Name: Sherman, Susan

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_

Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_

Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_

Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Inspector Name: Sherman, Susan

Overall Final Reclamation _____	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------------	--	--

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Remove stained soil at tank (see attached photo).	ShermaSe	06/23/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673713403	Renegade State 3 PA	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3885546">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3885546</a>