

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/24/2016

Document Number:

680400755

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	229034	336556	BROWNING, CHUCK	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON RDCity: RANGELY State: CO Zip: 81648

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Diane	970-675-3842	dlpe@chevron.com	Regulatory Specialist
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Compliance Summary:**QtrQtr: NWSW Sec: 17 Twp: 2N Range: 102W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/22/2014	668402247			SATISFACTORY	P		No
05/21/2013	668401258	IJ	IJ	SATISFACTORY	P		No
12/13/2012	668400844	IJ	AC	SATISFACTORY	P		No
05/21/2012	668400233	IJ	SI	ALLEGED VIOLATION			Yes
05/19/2011	200311312	RT	AC	SATISFACTORY			No
05/17/2010	200254436	RT	AC	SATISFACTORY			No
06/10/2009	200213929	RT	AC	SATISFACTORY			No
12/10/2008	200199995	RT	AC	SATISFACTORY			No
05/14/2007	200112313	RT	AC	SATISFACTORY		Pass	No
05/16/2006	200092003	RT	AC	SATISFACTORY		Pass	No
05/27/2005	200072684	RT	AC	SATISFACTORY		Pass	No
05/18/2004	200056142	RT	AC	SATISFACTORY		Pass	No
05/28/2003	200043416	RT	AC	SATISFACTORY		Pass	No
12/30/2002	200032734	RT	SI	SATISFACTORY		Pass	No
05/17/2001	200018532	MI	SI	ACTION REQUIRED		Fail	No
05/31/2000	200008992	RT	SI	SATISFACTORY		Pass	No
01/09/1998	500156803						

**Inspector Comment:**Routine UIC inspection.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
229033	WELL	IJ	05/27/2003	ERIW	103-06111	FAIRFIELD*KITTY A-1	IJ	<input type="checkbox"/>
229034	WELL	IJ	10/13/1992	ERIW	103-06112	FEE 24	AC	<input checked="" type="checkbox"/>
270499	PIT	AC	12/17/2003		-	FEE 115X	AC	<input type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: \_\_\_\_\_ Drilling Pits: \_\_\_\_\_ Wells: \_\_\_\_\_ Production Pits: \_\_\_\_\_  
 Condensate Tanks: \_\_\_\_\_ Water Tanks: \_\_\_\_\_ Separators: \_\_\_\_\_ Electric Motors: \_\_\_\_\_  
 Gas or Diesel Motors: \_\_\_\_\_ Cavity Pumps: \_\_\_\_\_ LACT Unit: \_\_\_\_\_ Pump Jacks: \_\_\_\_\_  
 Electric Generators: \_\_\_\_\_ Gas Pipeline: \_\_\_\_\_ Oil Pipeline: \_\_\_\_\_ Water Pipeline: \_\_\_\_\_  
 Gas Compressors: \_\_\_\_\_ VOC Combustor: \_\_\_\_\_ Oil Tanks: \_\_\_\_\_ Dehydrator Units: \_\_\_\_\_  
 Multi-Well Pits: \_\_\_\_\_ Pigging Station: \_\_\_\_\_ Flare: \_\_\_\_\_ Fuel Tanks: \_\_\_\_\_

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Main	SATISFACTORY			
Access	SATISFACTORY			

**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Spills:**

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Equipment:**

Type: Deadman # & Marked	# 4	Satisfactory/Action Required: SATISFACTORY
Comment		
Corrective Action		Date: _____

**Venting:**

Yes/No NO

Comment

**Flaring:**

Type Satisfactory/Action Required

Comment:

Corrective Action:

Correct Action

Date:

**Predrill**

Location ID: 229034

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

**S/AR:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 229034 Type: WELL API Number: 103-06112 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**Inj./Tube: Pressure or inches of Hg 1647  
(e.g. 30 psig or -30" Hg)Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
Inj Zone: WEBR

TC: Pressure or inches of Hg 5

Previous Test Pressure \_\_\_\_\_ Last MIT: 12/13/2012

Brhd: Pressure or inches of Hg 0

Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Routine UIC inspection. Active injection at time of inspection. Casing blowdown 5 sec.

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_

Tbg psi: \_\_\_\_\_

Csg psi: \_\_\_\_\_

BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Waste and Debris removed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_

CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass

CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass	SI	Pass	

Inspector Name: BROWNING, CHUCK

S/A/V: SATISFACTOR      Corrective Date: \_\_\_\_\_  
Y \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**    ☐ NO SURFACE INDICATION OF PIT

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680400755	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3887680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3887680</a>