



Photo 1. View of the project area from the northwestern corner facing center. The northwestern portion has been revegetated. Interim reclamation is needed in additional areas (southern and western) not needed for production operations.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Some desirable vegetation such as Indian ricegrass (*Achnatherum hymeniodes*) is becoming established on the cut-slopes.



Photo 3. View of the northwestern portion of the project area from the northwestern corner facing southward.



Photo 4. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 5. View of erosional channel that feeds into a bermed detention area (old pit?).



Photo 6. View of the southwestern portion of the project area from the southwestern corner facing northward. This area is vegetated largely with western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).