

Klaenhammer 2

Inspection# 673403305

Peeling label with previous operator. Vegetation on and in berm.



Previous operator on wellhead sign. Weeds on location and close to wellhead.

