

Interim Reclamation Inspection



Photo 1. Photo of Producing well sign for API #123-31080.

Interim Reclamation Inspection



Photo 2. Two List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*) and Musk thistle (*Carduus nutans*), exist throughout entire interim reclamation area.

Interim Reclamation Inspection



Photo 3. Photo taken from the southern location, facing South. Two List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*) and Musk thistle (*Carduus nutans*), exist throughout entire interim reclamation area.

Interim Reclamation Inspection



Photo 4. Photo taken from the southeastern location, facing South. Two List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*) and Musk thistle (*Carduus nutans*), exist throughout entire interim reclamation area.

Interim Reclamation Inspection



Photo 5. Photo taken from the eastern location, facing East. Two List B Colorado Noxious weed species, Canada thistle (*Cirsium arvense*) and Musk thistle (*Carduus nutans*), exist throughout entire interim reclamation area.

Interim Reclamation Inspection



Photo 6. Photo taken from the northwest location, facing East. Need to install sufficient stormwater and sediment control BMPs.

Interim Reclamation Inspection



Photo 7. Photo illustrating gulley forming off location and transporting sediment offsite. Need to install sufficient stormwater and sediment control BMPs.

Interim Reclamation Inspection



Photo 8. Photo taken from the southwest location, facing South, illustrating gully forming off location and transporting sediment offsite. Need to install sufficient stormwater and sediment control BMPs.